

Decatur Plant Operations
General Electric Company
2328 8th Street, S.E., P.O. Box 2223
Decatur, Al. 35609-2223
205-552-1305

June 5, 1989

Document Processing Center Office of Toxic Substances, TS-790 U.S. Environmental Protection Agency 401 M Street, S.W. Washington, D.C. 20460

90-890000403

Attention: CAIR Reporting Office

Gentlemen,

Find enclosed completed CAIR Reporting Form submitted as required under 40 CFR part 704 subpart D, for GE Decatur Alabama Plant Operations. If there questions concerning the data herein, please contact the undersigned at either 205-552-1354 or 205-552-1305.

Sincerely,

Paul E. Saywell, Jr.

Manager, Environmental, Safety & Health

cc: G.D. Caplinger

Mary Alice Brunner AP 26-101



Form Approved
OMB No. 2010-0019
Approval Expires 12-31-89



JW FAMS AD.

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Comprehensive Assessment Information Rule REPORTING FORM

When completed, send this form to:

Document Processing Center Office of Toxic Substances, TS-790 U.S. Environmental Protection Agency 401 M Street, SW Washington, DC 20460 Attention: CAIR Reporting Office For Agency Use Only:

Date of Receipt:

Document
Control Number:

Docket Number:

SECTION 1 GENERAL MANUFACTURER, IMPORTER, AND PROCESSOR INFORMATION PART A GENERAL REPORTING INFORMATION This Comprehensive Assessment Information Rule (CAIR) Reporting Form has been completed in response to the <u>Federal Register Notice of [7]2 [2]7 [8]8</u> CBI If a Chemical Abstracts Service Number (CAS No.) is provided in the Federal Register, list the CAS No. $[0]\overline{2}\overline{4}\overline{4}\overline{7}\overline{1}\overline{1}\overline{1}-\overline{6}\overline{2}\overline{1}-\overline{5}\overline{1}$ If a chemical substance CAS No. is not provided in the Federal Register, list either (i) the chemical name, (ii) the mixture name, or (iii) the trade name of the chemical substance as provided in the Federal Register. Chemical name as listed in the rule (ii) Name of mixture as listed in the rule (iii) Trade name as listed in the rule If a chemical category is provided in the Federal Register, report the name of the category as listed in the rule, the chemical substance CAS No. you are reporting on which falls under the listed category, and the chemical name of the substance you are reporting on which falls under the listed category. Name of category as listed in the rule Name of chemical substance 1.02 Identify your reporting status under CAIR by circling the appropriate response(s). CBI [-]Processor(3) X/P manufacturer reporting for customer who is a processor 4 [] Mark (X) this box if you attach a continuation sheet.

1.03	Does the substance you are reporting on have an "x/p" designation associated with it in the above-listed Federal Register Notice?
CBI	Yes $[\overline{\chi}]$ Go to question 1.04
[_]	No
1.04 CBI	a. Do you manufacture, import, or process the listed substance and distribute it under a trade name(s) different than that listed in the <u>Federal Register</u> Notice? Circle the appropriate response.
[_]	Yes
	b. Check the appropriate box below: NA
	$[\ \ \]$ You have chosen to notify your customers of their reporting obligations
	Provide the trade name(s)
	[] You have chosen to report for your customers
	You have submitted the trade name(s) to EPA one day after the effective date of the rule in the <u>Federal Register</u> Notice under which you are reporting.
1.05	If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name.
CBI	Trade name
[_]	Is the trade name product a mixture? Circle the appropriate response.
	Yes
	No
1.06	Certification The person who is responsible for the completion of this form must sign the certification statement below:
	"I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate."
	S. D. CAPLINGER DATE SIGNED PLANT MANAGER (205) 52 - 1200 TITLE TELEPHONE NO.
	PLANT MANAGER (205) TSZ - 1200 TITLE TELEPHONE NO.
[_]	Mark (X) this box if you attach a continuation sheet.

1.07 <u>CBI</u> []	Exemptions From Reporting — with the required information within the past 3 years, and for the time period specified are required to complete sect now required but not previous submissions along with your Submissions along with your Submissions which I have not to EPA within the past 3 year period specified in the rule.	this info this info d in the nation 1 of sly submit Section 1 he best of included as and is	IR Repormaticule, this ted. submi	orting Form for the on is current, accu then sign the certi CAIR form and provide a copy of ssion. Note that the control of the control of the call of	listed substance rate, and complete fication below. You de any information any previous , all required orm has been submitted
	NAME			SIGNATURE	DATE SIGNED
		,	,		
	TITLE	(TELEPHONE NO.	DATE OF PREVIOUS SUBMISSION
1.08 <u>CBI</u> [_]	CBI Certification If you he certify that the following st those confidentiality claims "My company has taken measure and it will continue to take been, reasonably ascertainable using legitimate means (other a judicial or quasi-judicial information is not publicly a would cause substantial harm	tatements which you es to prot these mea le by othe than dis proceedir available	truth tect to scover scover elsew	fully and accurately asserted. he confidentiality; the information is sons (other than go y based on a showing thout my company's there; and disclosure	y apply to all of of the information, s not, and has not vernment bodies) by g of special need in consent; the e of the information
	NAME			SIGNATURE	DATE SIGNED
	TITLE	()	TELEPHONE NO.	
	Mark (X) this box if you attac	ch a conti	nuati	on sheet.	

PART	B CORPORATE DATA
1.09	Facility Identification
<u>CBI</u>	Name [G]E]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
[_]	Address [2]3]2]8]] [1] [1] [1] [5] [1] [5] [1] [1] [1] [1] [1] [1] [1] [1] [1] [1
	[<u>]][][]A][][][]</u>][]][][][][][][][][][][][
	$[\overline{A}]\overline{L}] \qquad [\overline{3}]\overline{5}]\overline{6}]\overline{0}]\overline{4}]-[\overline{1}]\overline{2}]\overline{2}]$ State
	Dun & Bradstreet Number $\dots [\underline{1}]\underline{5}]-[\underline{5}]\underline{3}]\underline{o}]-[\underline{4}]\underline{8}]\underline{o}]\underline{I}]$
	EPA ID Number [A] L D 6 4 5 4 1 0 6
	Employer ID Number
	Primary Standard Industrial Classification (SIC) Code
	0ther SIC Code
	Other SIC Code
1.10	Company Headquarters Identification
CBI	Name [G] E]]]]]]]]]]]]]]]]]]
[_]	Address [3][]3]5]][][]A]5][][][]N][][][][][][][][][][][][][][][
	[F]A]_[R]F]_]E]_[D]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[<u>こ</u>]丁] [<u>0</u>]6] <u>4</u>] <u>3</u>] <u>「</u>][<u>]</u>] State
	Dun & Bradstreet Number $[0]0]-[1]3]6]-[7]9]6]0]$
	Employer ID Number
[_]	Mark (X) this box if you attach a continuation sheet.

1.11	Parent Company Identification
<u>CBI</u>	Name [<u>G</u>] <u>E</u>]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
[_]	Address [3][]3]5][E]A]5]T]o]N][]T]U]R]N]P]T]K]E]_]]]
	(至)百门区(至)工(至)区(五)二(二)二(二)二(二)二(二)二(二)二(二)二(二)二(二)二(二)二
	$ \begin{bmatrix} \boxed{2} \boxed{1} \\ \boxed{8} \end{bmatrix} \boxed{4} \boxed{3} \boxed{1} - \begin{bmatrix} \boxed{1} \end{bmatrix} \boxed{1} - \begin{bmatrix} \boxed{1} \end{bmatrix} \boxed{1} $ State
	Dun & Bradstreet Number $\dots [0]0]-[1]3[6]-[7]9]60$
1.12	Technical Contact
<u>CBI</u>	Name [P]A][[][][E][][S]A][Y][[][[][][][][][][][][][][][][][][]
[_]	Title [M]6 R] MIEIDI-IEINIVI-ISIAIFIEITIYI-IHIEIAILHIHI
	Address [2]3]2]8]-]8]+][]]5]T]-]5]E]-]-]-]-]-]-]-]-]-]-]-]-]-]-]-]-]-
	[页]至] <u>[[]][]][]</u> []][]][][][][][][][][][][][]
	[A]L] [3]5]66]9][2]2]2]3 State
	Telephone Number
1.13	This reporting year is from
[_]	Mark (X) this box if you attach a continuation sheet.

1.14	Facility Acquired If you purchased this facility during the reporting year, provide the following information about the seller:
an t	······································
<u>CBI</u>	Name of Seller [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	(_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_] [_]_]_]_]_][_]_]_]_]_]_] State
	Employer ID Number[_]]_]_]_]_]_]_]
	Date of Sale
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
1.15	Facility Sold If you sold this facility during the reporting year, provide the following information about the buyer:
CBI	Name of Buyer [_]_]_]_]_]_]_]_]_]_]_]_]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_] [_]_]_]_]_][_]]_]_] State
	Employer ID Number
	Date of Purchase
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
[_]	Mark (X) this box if you attach a continuation sheet.

lassification	
	Quantity (kg/yr)
anufactured	. N/A
	1.
	. N/A
	1.
	1/1
	1/1-
f that quantity processed, report that quantity:	**************************************
In storage at the beginning of the reporting year	28,723
	,
Processed as a formulation component (mixture producer)	. N/4
	. 0
Repackaged (including export)	. N/A
In storage at the end of the reporting year	0-
	rocessed (include quantity repackaged) f that quantity manufactured or imported, report that quantity: In storage at the beginning of the reporting year For on-site use or processing For direct commercial distribution (including export) In storage at the end of the reporting year f that quantity processed, report that quantity: In storage at the beginning of the reporting year Processed as a reactant (chemical producer) Processed as a formulation component (mixture producer) Processed as an article component (article producer) Repackaged (including export) In storage at the end of the reporting year ** In storage at the end of the reporting year ** In storage at the end of the reporting year ** In storage at the end of the reporting year

or a chemi each	or a component of a mixture, provide the following information for each component chemical. (If the mixture composition is variable, report an average percentage each component chemical for all formulations.)					
_}	Component Name	Supplier Name	Composition (specify	age % on by Weight precision, 5% ± 0.5%)		
			Total	100%		

2.04	State the quantity of the listed substance that your facility manufactured, imported, or processed during the 3 corporate fiscal years preceding the reporting year in descending order.
CBI	
[_]	Year ending
	Quantity manufactured N/A kg
	Quantity imported
	Quantity processed
	Year ending
	Quantity manufacturedkg
	Quantity imported
	Quantity processed
	Year ending
	Quantity manufactured kg
	Quantity imported
	Quantity processed
2.05 CBI	Specify the manner in which you manufactured the listed substance. Circle all appropriate process types.
[-]	
`'	Continuous process
	Semicontinuous process
	Batch process
[_]	Mark (X) this box if you attach a continuation sheet.

2.06 CBI	Specify the manner in appropriate process t		the listed substance.	Circle all
[_]	Continuous process .			1
	Semicontinuous process	s		2
				3
2.07 CBI	State your facility's substance. (If you a question.)			processing the listed , do not answer this
[_]				
				N/A kg/yr
	Processing capacity			2,227,277_ kg/yr
2.08 CBI	If you intend to incremanufactured, imported year, estimate the independent	d, or processed at an	y time after your cur	rent corporate fiscal
[-]		Manufacturing	Importing	Processing
		Quantity (kg)		
	Amount of increase	N/A	U/A	3,009,0904
	Amount of decrease	N/A	N/A-	N/4
			_	PLESSING CAPACITY FIRST FULL YR - 1990.
[_]	Mark (X) this box if y	ou attach a continua	tion sheet.	

2.09	listed substanc	argest volume manufacturing or processing procee, specify the number of days you manufactured go the reporting year. Also specify the average s type was operated. (If only one or two opera	or processed number of h	l the listed lours per
[<u>_</u>]			Days/Year	Average Hours/Day
	Process Type #1	(The process type involving the largest quantity of the listed substance.)	,	,
		Manufactured	<u> N/A</u>	NA
		Processed	191	<u>lb</u>
	Process Type #2	(The process type involving the 2nd largest quantity of the listed substance.)		. /^
		Manufactured	N/A	NA
		Processed	NA	NA
	Process Type #3	(The process type involving the 3rd largest quantity of the listed substance.)		,
		Manufactured	<u> </u>	A N
		Processed	_ NA	NA.
2.10 <u>CBI</u> [_]	State the maxim substance that chemical. Maximum daily i	um daily inventory and average monthly inventory was stored on-site during the reporting year in	y of the lis the form of	ted a bulk
	Average monthly	inventory	•	kg
[_]	Mark (X) this b	ox if you attach a continuation sheet.		

[<u></u>]	CAS No.	UNKNOWN Chemical Name	Byproduct, Coproduct or Impurity ¹	Concentration (%) (specify ± % precision)	Source of By- products, Co- products, or Impurities
	¹ Use the follo B = Byproduct C = Coproduct		e byproduct, copro	duct, or impurity	7:
	I = Impurity				

[_] Mark (X) this box if you attach a continuation sheet.

2.12 CBI []	Existing Product Types List all existing product types which you manufactured, imported, or processed using the listed substance during the reporting year. List the quantity of listed substance you use for each product type as a percentage of the total volume of listed substance used during the reporting year. Also list the quantity of listed substance used captively on-site as a percentage of the value listed under column b., and the types of end-users for each product type. (Refer to the instructions for further explanation and an example.)				
	a. b. % of Quan Manufactu Imported Product Types Process	red, l, or	% of Quantity Used Captively On-Site	d. Type of End-Users ²	
	**Juse the following codes to designate product the second that the second tha		= Moldable/Castabl = Plasticizer = Dye/Pigment/Colo = Photographic/Rep and additives = Electrodepositio = Fuel and fuel ad = Explosive chemic = Fragrance/Flavor = Pollution contro = Functional fluid = Metal alloy and = Rheological modi = Other (specify) e of end-users:	als and additives chemicals l chemicals s and additives additives fier	

<u>CBI</u>	import, or process using the listed substance at any time after your current corporate fiscal year. For each use, specify the quantity you expect to manufacture import, or process for each use as a percentage of the total volume of listed substance used during the reporting year. Also list the quantity of listed substance used captively on-site as a percentage of the value listed under column b., and the types of end-users for each product type. (Refer to the instructions for further explanation and an example.)						
	a.	b.		c.	d.		
	Product Types ¹	% of Quantity Manufactured, Imported, or Processed		of Quantity Used Captively On-Site	Type of End-Users ²		
		100		100	N/A		
			···				
				Programme and an action of the control of the contr			
	<pre>1 Use the following codes to A = Solvent B = Synthetic reactant C = Catalyst/Initiator/Acc</pre>	elerator/ Scavenger/ questrant greaser ifier/Antiwear	L = M M = P N = D O = P Q = F R = E S = F T = P U = F V = M W = R S X = O	doldable/Castable lasticizer by e/Pigment/Color by e/Pigment/Color by e/Pigment/Color by e/Pigment/Color by e/Pigment/Color by e/Pigment by e/Pigmen	als and additives chemicals l chemicals s and additives additives		
	Use the following codes to	designate the	type o	f end-users:			
	<pre>I = Industrial CM = Commercial</pre>	CS = Cons		cify)			

a.	b.	c. Average %	d.
		Composition of	_
Product Type ¹	Final Product's Physical Form ²	Listed Substance in Final Product	Type of End-Users
1	1	1	2110
N/A	N _A	N N	
¹ Use the following of	codes to designate pr		
A = Solvent		L = Moldable/Castable	/Rubber and add
<pre>B = Synthetic react C = Catalyst/Initia</pre>		<pre>M = Plasticizer N = Dye/Pigment/Color</pre>	ant/Ink and add
Sensitizer	(OI/Accelerator/	0 = Photographic/Repr	
D = Inhibitor/Stabi	lizer/Scavenger/	and additives	ographic chemic
Antioxidant		P = Electrodeposition	/Plating chemic
E = Analytical reag	ent	Q = Fuel and fuel add	
F = Chelator/Coagul		R = Explosive chemica	
G = Cleanser/Deterg		S = Fragrance/Flavor	
	ion modifier/Antiwea		
agent		<pre>U = Functional fluids</pre>	
I = Surfactant/Emul	sifier	V = Metal alloy and a	dditives
J = Flame retardant		W = Rheological modif	
<pre>K = Coating/Binder/</pre>	Adhesive and additive	es $X = Other (specify)$	
² Use the following o		e final product's physic	al form:
A = Gas		stalline solid	
B = Liquid	F3 = Grains		
C = Aqueous solution		ner solid	
D = Paste	G = Ge		
E = Slurry F1 = Powder	n = Oti	ner (specify)	
³ Use the following o	odes to designate the		
CM = Commercial		ner (specify)	

2.15 CBI	light	le all applicable modes of transportation used to deliver bulk shipments of ed substance to off-site customers.							
[_]	Truc	Truck							
	Rail	car	2						
	Barge	Barge, Vessel 3							
	Pipe:	line	4						
	Plane	e	5						
	Other	r (specify)	6						
2.16 CBI	or p	omer Use Estimate the quantity of the listed substance used by your customers during the reporting year for use under each cate and use listed (i-iv).							
[_]	Cate	gory of End Use							
	i.	Industrial Products							
		Chemical or mixture	kg/yr						
		Article	kg/yr						
	ii.	Commercial Products							
		Chemical or mixture	kg/yr						
		Article	kg/yr						
	iii.	Consumer Products							
		Chemical or mixture	kg/yr						
		Article	kg/yr						
	iv.	<u>Other</u>							
		Distribution (excluding export)	kg/yr						
		Export	kg/yr						
		Quantity of substance consumed as reactant	kg/yr						
		Unknown customer uses	kg/yr						
[_]		(X) this box if you attach a continuation sheet.							

PART	A GENERAL DATA		
3.01 <u>CBI</u>	Specify the quantity purchased and the average price for each major source of supply listed. Product trad The average price is the market value of the product substance.	les are treated as	purchases.
{ <u>□</u> 1	Source of Supply	Quantity (kg)	Average Price (\$/kg)
44 s	The listed substance was manufactured on-site.	N/A	N/4
	The listed substance was transferred from a different company site.	N/A	N/X
	The listed substance was purchased directly from a manufacturer or importer.	672,009	\$ 2.68
	The listed substance was purchased from a distributor or repackager.	NA	NA
	The listed substance was purchased from a mixture producer.	NA	NA
3.02 CBI	Circle all applicable modes of transportation used to your facility.	deliver the liste	ed substance to
[_]	Truck	• • • • • • • • • • • • • • • • • • • •	
	Railcar		2
	Barge, Vessel		3
	Pipeline		4
	Plane		5
	Other (specify)	• • • • • • • • • • • • • • • • • • • •	6
[_]	Mark (X) this box if you attach a continuation sheet.		

3.03 <u>CBI</u>	a.	Circle all applicable containers used to transport the listed substance to your facility.
[_]		Bags 1
		Boxes 2
		Free standing tank cylinders 3
		Tank rail cars 4
		Hopper cars 5
		Tank trucks
		Hopper trucks 7
		Drums 8
		Pipeline 9
		Other (specify)10
	b.	If the listed substance is transported in pressurized tank cylinders, tank rail cars, or tank trucks, state the pressure of the tanks.
		Tank cylinders
		Tank rail cars
		Tank trucks
[_]	Mar	k (X) this box if you attach a continuation sheet.

3.04 <u>CBI</u> []	If you obtain the listed substance in the form of a mixture, list the trade name(s) of the mixture, the name of its supplier(s) or manufacturer(s), an estimate of the average percent composition by weight of the listed substance in the mixture, and the amount of mixture processed during the reporting year.						
·	NA Trade Name	Supplier or Manufacturer	Average % Composition by Weight (specify ± % precision)	Amount Processed (kg/yr)			

3.05 CBI [_]	State the quantity of the lis reporting year in the form of the percent composition, by w	a class I chemical,	class II chemical, or polymer, and
,	Class I chemical	Quantity Used (kg/yr)	% Composition by Weight of Listed Substance in Raw Material (specify ± % precision CPRECISION UNKNOW)
	Class II chemical	Na	NA
	Polymer	NA	NA

	SECTION 4 PHYSICAL/CHEMICAL PROPERTIES					
Gener	al Instructions:					
If yo 4 tha	ou are reporting on a mixt It are inappropriate to mi	ure as de xtures by	efined in th stating "N	e glossary A mixtu	, reply to	questions in Section
notic	uestions 4.06-4.15, if yo e that addresses the info mile in lieu of answering	rmation 1	requested, y	ou may subr	nit a copy	abel, MSDS, or other or reasonable
PART	A PHYSICAL/CHEMICAL DATA	SUMMARY				
4.01 <u>CBI</u>	Specify the percent puri substance as it is manuf substance in the final p import the substance, or	actured, roduct fo	imported, o orm for manu	r processed facturing a	d. Measure activities,	e the purity of the at the time you
ι,	Taluial and #1	<u> </u>	acture _% purity	A//A	port % purity	Process CRUE/
	Technical grade #1	1	_	1/4	_% purity % purity	UNNSTILLED % purity
	Technical grade #2 Technical grade #3	.1	_% purity _% purity	NA	_% purity _% purity	N/A purity
	¹ Major = Greatest quanti	ty of lis	sted substan	ce manufac	tured, impo	orted or processed.
4.02	Submit your most recently updated Material Safety Data Sheet (MSDS) for the listed substance, and for every formulation containing the listed substance. If you possess an MSDS that you developed and an MSDS developed by a different source, submit your version. Indicate whether at least one MSDS has been submitted by circling the appropriate response.					
	Yes					(1
	No					2
	Indicate whether the MSD	S was de	veloped by y	our company	y or by a d	lifferent source.
	Your company			• • • • • • • • • •		1
						_

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

4.03	Submit a copy or reasonable facsimile of any hazard information (other than an MSDS) that is provided to your customers/users regarding the listed substance or any formulation containing the listed substance. Indicate whether this information has been submitted by circling the appropriate response.
	Yes 1
	No
4.04	For each activity that uses the listed substance, circle all the applicable number(s) corresponding to each physical state of the listed substance during the activity

4.04 For each activity that uses the listed substance, circle all the applicable number(s) corresponding to each physical state of the listed substance during the activity listed. Physical states for importing and processing activities are determined at the time you import or begin to process the listed substance. Physical states for manufacturing, storage, disposal and transport activities are determined using the final state of the product.

[___]

			Physical State					
Activity		Sol	id Slurr	y Liquid	Liquifi Gas	ed Gas		
Manufacture	NA	1	. 2	3	4	5		
Import	NB	1	. 2	3	4	5		
Process		1	. 2	<u>3</u>	4	5		
Store		1	. 2	(3)	4	5		
Dispose		$\overline{1}$	2	3	4	5		
Transport	NA	1	. 2	3	4	5		

[_] Mark (X) this box if you attach a continuation sheet.

I listed s storage;]	state o	of the pro	cturing duct.				
Physical State	NA	Manufacture	Import	Process	Store	Dispose	Transport
Dust	<1 micron						
	1 to <5 microns						
	5 to <10 microns						
Powder	<1 micron						
	1 to <5 microns						
	5 to <10 microns						
Fiber	<1 micron						
	1 to <5 microns	 					
	5 to <10 microns						
Aerosol	<1 micron						
	1 to <5 microns	<u> </u>					
	5 to <10 microns						

MKI F	- A	RATE CONSTANTS AND TRANSFORMATION PRODUCTS		
.01		Photolysis: LNKNOUN	rmation processes.	
	a.			
		Absorption spectrum coefficient (peak)		
		Reaction quantum yield, 6		
		Direct photolysis rate constant, k _p , at	1/hr	latitude
	b.	Oxidation constants at 25°C: UNKNOWN		
		For 10_2 (singlet oxygen), k_{ox}		1/M hi
		For RO_2 (peroxy radical), k_{ox}		1/M hi
	c.	Five-day biochemical oxygen demand, BOD ₅ <u>UNK</u>	NOWN	mg/l
	d.	Biotransformation rate constant: UNKAMMIN		
		For bacterial transformation in water, k _b		1/hr
		Specify culture		····
	e.	Hydrolysis rate constants: LNKNOWN		
		For base-promoted process, k_B		1/M hr
		For acid-promoted process, k _A		1/M hr
		For neutral process, k _N		1/hr
	f.	Chemical reduction rate (specify conditions) UN	KNOWN	-
	g.	Other (such as spontaneous degradation)		

[_] Mark (X) this box if you attach a continuation sheet.

PART	ВР	PARTITION COEFFICIEN	its					
5.02	a.	Specify the half-l	ife of the	listed substa	ance in the	following	media.	
		<u>Media</u>			Half-life	(specify	units)	-
		Groundwater		Luknou) N			
		Atmosphere		UNRIVO				
		Surface water		WHEN	1			
		Soil		LINKN	1			
	b.	Identify the liste			V VV	products	that ha	ve a half-
		CAS No.	nnku	Name	Half-li (specify			<u>Media</u>
		- Address of the Control of the Cont	·				in	
							in	
					- ****		in	
							in	
5.03		cify the octanol-wa				HNK	NowN	at 25°0
5.04		cify the soil-water						
5.05	Spe coe	cify the organic ca fficient, K _{oc}	rbon-water	partition		unkn	own	at 25°C
5.06	Spe	cify the Henry's La	w Constant,	н		unknog	UN	atm-m³/mole
[_]	Mar	k (X) this box if y	ou attach a	continuation	n sheet.			

Bioconcentration Factor UNKNOWN Species	<u>Test¹</u>
 ¹ Use the following codes to designate the type of test:	
<pre>F = Flowthrough S = Static</pre>	

6.0 CBI	For each market listed below, state the the listed substance sold or transferr	e quantity sold and the	total sales value of
	The rest of the second	Quantity Sold or	Total Sales
	Market	Transferred (kg/yr)	Value (\$/yr)
	Retail sales	/	
	Distribution Wholesakers		
	Distribution Retailers		
	Intra-company transfer		
	Repackagers		
	Mixture producers		
	Article producers		
	Other chemical manufacturers or processors		
	Exporters		
	Other (specify)		
_			
6.05 <u>CBI</u> [_]	Substitutes — List all known commercifor the listed substance and state the feasible substitute is one which is ed in your current operation, and which reperformance in its end uses. COMMERCIAL FEASIBLITY OF SUBSTITUTE	cost of each substitute onomically and technologe esults in a final produc	e. A commercially gically feasible to use ct with comparable
[_]	Mark (X) this box if you attach a cont	inuation sheet.	

SECTION	7	MANUFACTURING	AND	PROCESSING	INFORMATION

General Instructions:

For questions 7.04-7.06, provide a separate response for each process block flow diagram provided in questions 7.01, 7.02, and 7.03. Identify the process type from which the information is extracted.

PART A MANUFACTURING AND PROCESSING PROCESS TYPE DESCRIPTION

7.01 In accordance with the instructions, provide a process block flow diagram showing the major (greatest volume) process type involving the listed substance.

CBI

[] Process type SEE ATTACHED FLOW CHARTS (7.0/A


- FORM BULK CHEMICAL SYSTEMS -PAGE 42A)


AND 7.01 B

- CASE/DOOR FOAM SYSTEM

PAGE 42B

 $^{[\}overline{\kappa}]$ Mark (X) this box if you attach a continuation sheet.





7.03	In accordance with the instructions, provide a process block flow diagram showing all process emission streams and emission points that contain the listed substance and which, if combined, would total at least 90 percent of all facility emissions if not treated before emission into the environment. If all such emissions are released from one process type, provide a process block flow diagram using the instructions for question 7.01. If all such emissions are released from more than one process type, provide a process block flow diagram showing each process type as a separate block.
	

CBI

Process type 7.0H FOAM BULK CHEMICAL SYSTEMS

PLEASE REFER to PAGE 42A FOR Flow ID

TDI EMISSIONS

7.2 FILTER VENT (ALSO VENTS PLIMP STAND)

7.6 DRY ABSORBER VENT

7.9 FILTER VENT

 $^{[\}underline{x}]$ Mark (X) this box if you attach a continuation sheet.

7.03	In accordance with the instructions, provide a process block flow diagram showing all
	process emission streams and emission points that contain the listed substance and
	which, if combined, would total at least 90 percent of all facility emissions if not
	treated before emission into the environment. If all such emissions are released
	from one process type, provide a process block flow diagram using the instructions
	for question 7.01. If all such emissions are released from more than one process
	type, provide a process block flow diagram showing each process type as a separate
	black

CBI

[] Process type 70 B CASE / DOOR FOAM SYSTEM

PLEASE REFER TO PAGE 428 FOR FLOW ID

TDI EMISSIONS.

- 7.32 TDI DAY TANK VEUT (DOOR)
- 7.36 FILTER VENT (TOIL)
- 7.38 TOI FILTER VENT
- 7.40 TOIL METERING PLIMP STAND VENT
- 7.42 DOOR FOAM SYSTEM VENT
- 7.50 TOI DAY TANT VENT (CASE LINE)
- 7.54 TOI FILTER VENT
- 7.55 TOI METERING PLIMP STAND VENT
- 7.58 TOI CALIBRATION STAND VENT
- 7.60 TOI CASE FORM SYSTEM VENTS (4)

NOTE: NOT SHOWN IS AN EMERGENCY VENT FOR WORKER PROTECTION - LOCATED NEAR 7.48 AND 7.51

[[]_] Mark (X) this box if you attach a continuation sheet.

7.04 Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

<u></u>	Process type	7.01A FOAN BULK CHEMICA	CHEMICAI	Systems	•		
·′			ΓDΤ				

	・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・			
Uni t			Operating	
Operation	Typical	Operating	Pressure	
ID	Equipment	Temperature	Range	Vessel
Number	Type	Range (°C)	(mm Hg)	Composition
7A	BAIL U/VALUE	AMBIEUT-40	2585	STEEL
7.1 科	Ter FSI 15 K	3z-38	3878	Bas/Aber
7.2	DUCT /EXTERNAL	ANBIENT-32	EST 1500	STEEL
7.3	TANK 6000 G	32-38	3878	STEEL
7.4	COMPRESSOR	र् _{ग 32}	103	STEEL
7.5	ODOR MISER ACT. CHARCOLL	ANDIENT-32	103	STEEL
7.6	A" PIPE + RELIEF /VALUE	AMBIENT -32	103	STEEL
7.7	VIKING / STALESS MAG DRIVE	32-38	3878	<u> Fier</u>
7.8	F51 25 M	32-38	3878	BAG/11Ber
7.9	DUCT /EXTERNAL	AMBIENF32	CAT 1500	258EL
7.10	PLATE	32-38	3878	STEEL _

 $^{[\}overline{Z}]$ Mark (X) this box if you attach a continuation sheet.

7.04 Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

[_] Process type	7.01 B CASE/	DOOR FOAM	SYSTEM
------------------	--------------	-----------	--------

Unit	TDI	Operating		
Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Pressure Range (mm Hg)	Vessel Composition
7.30	500 6 TANK	32-38	2068	STEEL
7.31	COMPRESSOR	E51 32	103	STEEL
7.32	DUCT/EXTERNAL	AMBIEN 32	EST 1530	STEEL
7.33	VIKING / POSITIVE DIS PLACEMENT	32-38	2068	STEEL
7.34	CUND MULTIPLITE SCRAFER	32-39	2068	STEEL
7.35	ESI WH	32-38	2068	STEEL BAG/FIBER
7.36	DUCT EXTERNAL	AMBLENT-32	EST ISOU	STEEL
7.37	F51 25 µ	37-36	2068	STEEL THE
7.3B	DUCT LEXTERNAL	AMBIENT-32		STEEL
7.34	RAM (METERING)	37-38	5171-77,565	STEEL

 $^{[\}overline{x}]$ Mark (X) this box if you attach a continuation sheet.

7.04	process black	typical equipment types flow diagram(s). If a ess type, photocopy this	process block flow	diagram is pro	vided for more
CBI	process type.		/	_	,
,	Process type	701B	CASE DUOR	FORM 2	YSTEM
lJ	riocess type		•		
	II i a	TOI	L	Operating	
	Unit Operation	Typical	Operating	Pressure	
	ID	Equipment	Temperature	Range	Vessel
	Number	Type	Range (°C)	(mm Hg)	Composition
•	7.40	DUCT EXTERNAL	AUDIENT	EST 1500	STEEL
	7.41	POUR HEAD	32-36	5171-17.56	STEEL/Alloy
	7A2	DIST/ EXTERNAL	MUBIENT	E5T 1500	STEEL
	7.43	ERROR-DELETE	£-'		
	7.48	TANK 1000 G	32-38	1068	STEEL
	7.49	Lomp Ressor	EST 32	103	STEEL
	7.50	DUET/EXTERNAL	AMBIENT	EST ISON	STEEL
	7.51	PumP	32-38	2061	STEEL
	7.52	CUNO MUITIPLATE SCRAPER	32-38	2068	STEEL
	7.53	FS1 25 M	32-38	2068	BAC/FIDER

[[]X] Mark (X) this box if you attach a continuation sheet.

7.04	process block	typical equipment types fo flow diagram(s). If a pr cess type, photocopy this q	ocess block flow	diagram is provid	ded for more
<u>CBI</u>	process type.		1		
[_]	Process type		E DOOR FOR	am Dystem	
		TOI			•
	Unit Operation	Typical	Operating	Operating Pressure	
	ID	Equipment	Temperature	Range	Vessel
	Number	Type	Range (°C)	(mm Hg)	Composition
	7.54	DUCT/EXTERNAL	AMBIEUT-32	EST ISDO	STEEL
	7.55	DUCT/EXTERNAL	AMBIEUT-32	EST ISOD	STEL
	7.56	viking stalks magnetic druk,	38-38	5171-11565	3846
	7.57	THIECTIM HEAD /BOOTH	32-38	511-77,545	STEEL STRIVICS
	7.58	DUCT/EXCLAUST	AMAISNT-52	EST 1500	STEEL
	7.59	FORM STATION/IND. Injection · Spec. Design	32-38	5171-77565	TEEL/STAINL
	7.60	DUCT/EXHAUST	ANBIENT -32	45T 1500	STEEL
				-	

<u>CBI</u>	process type				
[_]	Process type		FOAM BULK C	Hemical Dys	STEMS
		Polyol.			
	Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Operating Pressure Range (mm Hg)	Vessel Composition
	7.B 7.11	BALL U/VAIVE VIKING ESI 251 FILTER	Ambieut-38	2585 2500-4000 2500-4000	STEEL BAG/FIBER
	7.12	TANK 6000 G	ANDIEUT-38	2600-4000	STEEL
	7.13	DUCT/EXTEENM	ANDIEUT	255 1500	STEEL
	7.14	Viking + Dis.	AMBIENT-38	1500-4000	STEEL
	7.15	F51 25 pc	AMBIENT-38	1500-4000	BAG/FIBS

7.04 Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. CBI

[_]	Process	type	• • • • • • • •	7.01 A	FOAM	Bulk	CHEMICAL	SYSTEMS	·
				ADA	ITIVES				

Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Operating Pressure Range (mm Hg)	Vessel Composition
7.23	POSITIVE DISP	AMBIEUT	43000	518EL
7.24	TANK 80006	AMBIEUT	13000	STEEL
7.25	VIKING + DISP	AMBIEUT	4 3006	STEEL
7.26	TAUK 6000G	AMBIENT- 32-	Atmosphere	STEEL
7.27	NOTIVATED CHARGON	ANBIETT-32	103	STEEL
7.28	DUCT /EXHAUST	MUDICAT. 32	EST 1500	TIEEL
7.26A	Pump - uikingt dis	AMBIENT-32	-4000	STEEL
7.29	BUCT/EXHMUST	AUBIENT	44000	SPEEL

Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. CBI 7.01A FORM BULK CHEMICAL SYSTEMS "MASTER BATCH "OR COMPONENT "B" Operating Unit Pressure Typical Operating Operation Vessel Range Temperature Equipment ID Composition Range (°C) (mm Hg) Number Type 44000 STEEL tank - 6000 61L 7.1b STEEL VIKING + DIS 15-38 7.11 BAG/FIBER AMBIECT.32 EST 1500 EXHAUST STEEL 6000 646 4000-70,000 25-38 STEEL iking + bis STEEL 25-38 44000 PLATE

 $^{[\}nearrow]$ Mark (X) this box if you attach a continuation sheet.

7.04 Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

[_]	Process type	• • • • • • •	7.01B	CASEL	DOOR	FOAM	SYSTE	M	
			" M4:	STERBAZ	ct" OF	COMA	TUBLIC	B4	

	.1145.2	ADMICH DID OF	1.0000.	
Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Operating Pressure Range (mm Hg)	Vessel Composition
7.43	TANK 6000G	26.38	-4000	STEEL
744	DUCT/EXHAUST	AUDIENT- 32	EST 1500	STEEL
7.45	VIKING + DIST.	25-38	4000	STEEL
7.46	Fot 25m	25.38	44000	STEEL BAG/FIBER
7.47	VIKING + DISP.	25.38	4000-70,000	STESI
7.6	TANK 60006	75-38	14000	STEEL
7.62	DUCT/EXHAUST	AMBIECT-32	EST 1500	STEEL
7.63	viking + disp.	15.38	-4000	STEEL
7.64	FOI asu	25-38	4000	STEEL BAGIFIBER
7.65	Viking + DIST.	25-38	4000-10,006	STEEL

 Process type	7.01B			
Unit Operation ID Number 7.66 7.67	Typical Equipment Type INTECTION HEAD BOODIGITAL WEIGH-MO	Operating Temperature Range (°C) TH BAY 35-38 AUDIEUT-37	OmboNeNT "B Operating Pressure Range (mm Hg) 4000-70,00	Vessel Compositio

			-	

7.05	Describe each process stream identified in your process block flow diagram is provided for more t question and complete it separately for each process.	han one process type	iagram(s). If a e, photocopy this
CBI			
	Process type 1019 FOAM Bulk	Chamian Sie	TEME
l_]	Process type	MILLIAN SAS	I ENZ
	Process		
	Stream		0
	ID Process Stream Code Description	Physical State ¹	Stream Flow (kg/yr)
			, ,
	(7H, 7J, 7N, 70 BULK TD)		672,009
	(7Q,7R		
	7 I, 7 L, 7 M, 7 P EXHAUST DUCTS; QULK TO	6C	NIL
	75, 7T, 7V, 7W, 7x Polyol	<u>o</u> L	594,372
	74 Polyol TANK UZNI	GU	NIL
	TFF, TGG, THH, TII RII		
	(7JJ, 7MM POLYCAT'S" CATALYST (BELK)	<u>e</u> L	(21.709
		61 11	1
	CTHN + OTHER ADDITIVES	OL, AL	
	¹ Use the following codes to designate the physica	al state for each pro	ocess stream:
	GC = Gas (condensible at ambient temperature and	l pressure)	
	GU = Gas (uncondensible at ambient temperature a	ınd pressure)	
	SO = Solid SY = Sludge or slurry		
	AL = Aqueous liquid		
	OL = Organic liquid	109 taluan	~ \
	IL = Immiscible liquid (specify phases, e.g., 90	% water, 10% torden	e)

7.05	process block	process stream identified in your parties of the first separately for each process of the process of the first separately for each process of the first separate	than one process tyl	iiagram(s). If a be, photocopy this
<u>CBI</u>		- 2	1 1	
[_]	Process type	7.01 A FOAM B	ulk Chemicals	
	Process Stream ID	Process Stream	Physical State ¹	Stream Flow (kg/yr)
	Code	Description Rescription Rule 14		anknowy
	<u>7KK</u>	Ydycat "8" CATALYST BULK VE	GC GC	_
	JLL_	Stolyest & "Scrubber (DEY)		NIL
	,	VEUT		1.101
(7 <u>4,72, 7 A A</u> ,	"MAJTER BATCH"OR	OL	616,081
₹	7 <u>88,7८८,7</u> 01	Comtoness B		
Į	TEE .)		 -
	7.00	ADUITIVE EXHAUST DUCT	OL, AL	<u>unknow</u>
				-
	GC = Gas (cor GU = Gas (und SO = Solid SY = Sludge of AL = Aqueous	liquid	d pressure) and pressure)	

7.05	Describe each pr	ocess stream identified in your	process block flow dia	gram(s). If
	process block fl	ow diagram is provided for more of plete it separately for each product.	than one process type,	pnotocopy tn
CBI			France Current	
[_]	Process type	7.01 B CASE / DOOR	TOAM SYSIEM	
	Process Stream			
	ID Code	Process Stream Description	Physical State	Stream Flow (kg/yr
	7R,7RR,755	DOOR LIVE TO SYSTEM	<u>or</u>)	• • • • • • • • • • • • • • • • • • • •
	• •	DOOR LINE TO SYSTEM	OL	
	7kkk,7LLL,7mmi	CASE LINE TO SYSTEM	OL }	672009
	7000, 7RRR, 755	S CASE LINE TO SYSTEM	oL	
	7TT	CASE LINE TOI SYSTEM	<u>ol</u>	
	700,744,7WW	DOOR LINE TO I EXH VENTS	<u>6</u> C	~1
THA	7 <u>27,788<i>0</i></u> 7000 ,7000,700	DODE LINE TO EXH VENTS	<u>& </u>	34
رددل	7ESE TERM	CASE LINE TO 1 EXH VENTS	<u>6</u> C	
	GC = Gas (conde GU = Gas (uncon SO = Solid SY = Sludge or AL = Aqueous li	quid	d pressure) and pressure)	

7.06 CBI	If a proces this questi	e each process stream ide s block flow diagram is p on and complete it separa s for further explanation	provided for mor ately for each p	re than one pro process type.	cess type, photocopy
[_]	Process typ	e 7,01A	FOAM BULL	CHEMICAL	SYSTEMS
	a.	b.	c.	d.	e.
	Process Stream ID Code	Known Compounds ¹	Concen- trations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
74,73	1,7N,70,	TOT CASHO26471-62-5 PREPOLYMEN OF TO I AND PRO-	60%	NA	N/A
	a,7R *	POXILLATED GLUCERINE	10-30%	N/N	NA
		PREPOLYMER OF TOI AND PRO POWYLATED SUCROSE	10-3000	NIN	NA
)
	7I,7L,7F	SAME AS ABOUE	EST 4 1 PPM	NONE	NA
	7M	SAME AS ABOVE	NIL	NONE	N/A
7.06	continued b	 elow			
	.4	★ CAS # 039279-	•		
	*	.* Cas# 059154.	-64-2		

7.06 CBI	If a process this questions instructions	e each process stream iders block flow diagram is pron and complete it separates for further explanation	covided for mor cely for each p and an example	rocess type. ((Refer to the
[_]	Process type	7.014 Fot	im Bulk Ch	<u>emical Syst</u>	ems
	a.	b.	c.	d.	е.
	Process Stream ID Code	Known Compounds ¹	Concen- trations ² , ³ (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
75	77,70 *	BLEND of POLYETHER POLY	ols unknown	NA	WIN
		BLEND OF TERTIARY AMINES	unknowp)	NA	NA
	<u> 14</u>	same as above	บมหมอนฟ	N/A	N/A-
	7 55,766 744	R-11	100%	NONE	NONE
7.06	continued b	5-01 01 0	**	CAS #5 0	00111-40-0 00105-59-9

-1	Process type	for further explanation	OAM Bulk		systems
1	a.	b.	c.	d.	e.
	Process Stream ID Code	Known Compounds ¹	Concen- trations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
		N'N DIMETHY CYCLUMENY	100	NIA	UH
		LUIDE			
	1		· ·	A	4/4
	7NN	SILICONE	100%	<u> </u>	4/16
		DIBUTYL TIN DILAURA		<i>W/'''</i>	
		WLTER			
					_
	continued be	al av			
06	Continued be	EIOM			

[\mathbf{X}] Mark (X) this box if you attach a continuation sheet.

[_]	Process type			on and an examp	FOAM SYSTE	Μ
	a.	ь.		c.	d.	e.
	Process Stream ID Code	Known Com	pounds ¹	Concen- trations ² , (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
IR, TR	R,755,711, 1 4x,744, 2	DI CASTO	FTDI AND		NONE	
		Porylated a Prepaymen			NUNG	- M/A
mmm 355 7	,7000,7RRR	Poyglated	sullose	10-309/		
7 <i>9</i> &7	_ սվ, 7ww	SAME	45 +8012	EST L I PPM	NONE	N/A
- •	BBB,7JJJ					
	7000,7UU	Ц				
7 EE	E					

 $[\mathbf{X}]$ Mark (X) this box if you attach a continuation sheet.

	s for further explanat			em .
_	b.	c.	d.	e.
Process Stream ID Code	Known Compounds ¹	Concen- trations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
000, 7 EEE , 1FF	N.N DIMETHYLOICIGH	EM AMINE)		
666,7HHH,	DIBUTYL TIN DILAURA	TE _		
www, 7xxx, 1yyy, 7aaa, 18888, 7ddod	SILIEONE 5340	100%	NONE	NA
772	Polyol	_)		
ILLU , TCCCC	JANE AS A BOVE	- Juknown	NONE	N/#
iddb, racu				
7.04				
7.06 continued	Delow			

7	06	(con			٠.
/ .	UD	(con	T 1	nue	a ı

¹For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column b. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive ackage Number	Components of Additive Package	Concentrations (% or ppm)
1	SILICONE 5340	0.01%
	N·N· crelokery Amile	0.02%
	DIBUTYL TIN DILAURATE	0.002 %
<u></u>	WATER	41%
3		
4		
5		

 $^{^{2}}$ Use the following codes to designate how the concentration was determined:

A = Analytical result E = Engineering judgement/calculation

V = Volume W = Weight

|--|--|

 $^{^{3}}$ Use the following codes to designate how the concentration was measured:

PART	A RESIDUAL	L TREATMENT P	ROCESS DESCRIPTION	1	
8.01 CBI	In accorda which desc	ance with the cribes the tr	instructions, pro eatment process us	ovide a residual sed for residuals	treatment block flow diagram identified in question 7.01.
[_]	Process ty	ype			
	7A-7F		drum storage.	OFF SITE RESIDUALS (INCINER	MGMWT ATTON

PART B RESIDUAL GENERATION AND CHARACTERIZATION

8.05 <u>CBI</u> [_]	diagram process	(s). If a in type, photo (Refer to the	esidual tre ecopy this que instructi		low diagram is uplete it sepand explanation CHEMICAL SEPAND STAND	provided for rately for each an example	more than on th process
	a.	b.	c.	d. Tol	- e.	f.	g.
IN, T TRR, TXX	Stream ID Code 71,71,7 0,70,7R 755,711, 144,74	70V	Physical State of Residual ² Solid	Known Compounds ³ REACTED 2-4 TDI 4ND 2-6 TDI	Concentra- tions (% or ppm) ^{4,5,6} Est loods	Other Expected Compounds	Estimated Concentrations (% or ppm)
7M MI 7QQQ 1555, SA AS	1, 1000, 1 , 7 R.R.B., 7 HT	PT	LIQUID (OL)	TD1 02647162;	60 10 10	revknown	N/4-
noc				Prepdymer of TOI AND PREPOX. 944 ceru	we 10-30%	UNKNOWN	~/4
8.05	continue	d below		5 ARE IDEN		PROCESS	STREAU,

[_]	Mark (X)	this box is	f you attach	a continuatio		Plushing Aga Location	AT AT THIS
	continued	·		ocess typ	44 1	Process STR nothlylene Ch Inusual Conti HERE. IT 15	Lotide is all HAINAUT NOT 4
						AND	
		7277		WITER	41%		
				DIBUTYLTIN DILAURATE	41%	-	
				SILICONE	EST 4 1%		
, צצדו,	122,7A 70000	AAA >		N·N OINCTHYL CYCLO h CX4 Aa	0-18%		
IWWW	D,762,			R-11	EST 20%	(10) 0 (10)	
74,7A	1 <u>v,7w,</u> 7 <u>x</u> A,78B,	N/4	OL	POLYETHER PR TERTIARY MULL	•	B Menbrove" CHIORIDE (Possible)	0-5870
	Stream ID Code	Type of Hazardous Waste	Physical State of Residual ²	Known Compounds ³	Concentra- tions (% or ppm) ^{4,5,6}	Compounds	Estimated Concen- trations (% or ppm)
	a.	b.	с.	d.	е.	f.	g.
[_]			7.01 A	FOAM BULK CASE/DOOR	CHENICAL S	YSTEMS AND	*
CBI	process	type, photo	ocopy this q	uestion and co	mplete it se	parately for each and an example	ch process
8.05	Characte	erize each p	process stre	am identified	in your resident	dual treatment is provided for	block flow

8.05 (continued) ¹Use the following codes to designate the type of hazardous waste: I = Ignitable C = Corrosive R = Reactive E = EP toxicT = ToxicH = Acutely hazardous ²Use the following codes to designate the physical state of the residual: GC = Gas (condensible at ambient temperature and pressure) GU = Gas (uncondensible at ambient temperature and pressure) SO = SolidSY = Sludge or slurry AL = Aqueous liquid OL = Organic liquid IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene) 8.05 continued below

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

6.05 (continued)	8.05	(continued)	
------------------	------	-------------	--

³For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column d. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

	Additive Package Number	Components of Additive Package	Concentrations (% or ppm)
	1	SILICONE S340	0.01 %
		DIBUTYL TIN DILAURATE	0.002
		water	41 %
	2		
	3		
			
	4		
	5		
	⁴ Use the following code:	s to designate how the concentration w	vas determined:
	A = Analytical result E = Engineering judgement	ent/calculation	
8.05	continued below		
[_]	Mark (X) this box if you	u attach a continuation sheet.	
		56	

⁵ Use the	following codes to designate how the concentration was mo	easured:
V = Vol		
W= Weig		
⁶ Specify	the analytical test methods used and their detection lime. Assign a code to each test method used and list those code	its in the tab
perow.	Assign a code to each test method used and list those cod	les III Column
		Detection
Code	Method	(± ug/
_1	CHENICAL ANALYSIS - METHOD WARNOWN	MNKNOU
2		
3		4200
4		
5		
6		

	type.	(Refer to the	instructio		ner explan	ation and	an example.))
<u>CBI</u>			7.01	A FOAM	BULK C	HEMICAL	SYSTEMS	1
[_]	Process	type	7.01	B CASE/	DOOR FO	DAM JYS	TEMS	
	a.	b.	с.	d.	е		f. Costs for	g.
	Stream ID Code	Waste Description Code	Management Method Code ²	Residual Quantities (kg/yr)		gement dual (%) Off-Site	Off-Site Management (per kg)	Changes in Management Methods
	<u>7xx</u>	B69	3I/2I	735	0	100%	\$3.80	
7H-71	77,7N			***************************************	<u></u>			
70,71	27 R, 7F	48 VV,7xx,7yy						
HAR,	7 <u>kkk,7</u> L ,7000,71	LL B82/84	2 I	4725	0	100%	+ 4.36	
7555,7	TT	<rr< td=""><td></td><td></td><td></td><td></td><td></td><td></td></rr<>						
75,71	77V,7W			denomination of the second				
7x,77	,744,78 188,70D	B,7CC						
7FFF,	7666,7 17xxx	444,						
7477,	7222, 4,7888F	*	31/z1	2564	_0	100%	\$0.94	
7 001	, –	,						
		e codes provi e codes provi						
	Δ	etes na i	ne est sa	7./ 75		40	et as Note	

[_]		Ch	ustion amber ture (°C)	Temp	tion of erature nitor	In Com	nce Time bustion (seconds)
	Incinerator 1	Primary	Secondary	Primary	Secondary	Primary	Secondary
	3				/		
		ing the app	of Solid Wast ropriate resp		s been submit	ted in lieu	of response 1
	No			/	./		2
8.23 <u>CBI</u> [_]	Incinerator 2	te to burn	the residuals ram(s). Air Po	llution Device	in your proc	Types Emission Avail	residual of s Data
		ing the app	ropriate resp	onse.	s been submit		-
	Yes		• • • • • • • • • • • • • • • • • • • •	••••••			1

PART A EMPLOYMENT AND POTENTIAL EXPOSURE PROFILE

9.01 Mark (X) the appropriate column to indicate whether your company maintains records on the following data elements for hourly and salaried workers. Specify for each data element the year in which you began maintaining records and the number of years the records for that data element are maintained. (Refer to the instructions for further explanation and an example.)

]	explanation and an enample,				
	Data Element	Data are Ma: Hourly Workers	intained for Salaried Workers	: Year in Which Data Collection Began	Number of Years Records Are Maintained
	Date of hire	X	<u> </u>	<u>1973 (co 195</u> 0	(5) 10
	Age at hire	<u> </u>	<u> </u>	1973 (101950	ś <u>) 10</u>
	Work history of individual before employment at your facility	<u>*</u>		1973	£5T10
	Sex	X			_10
	Race	X	X	1973	
	Job titles	_×	×	EARLY 19805	(0
	Start date for each job title	×	<u> </u>	EARCY 19885	10
	End date for each job title		X	EARLY 1980'S	10
	Work area industrial hygiene monitoring data	_X_	X	1977 *	30
	Personal employee monitoring data	<u> </u>	<u> </u>	1983	30
	Employee medical history	<u> </u>	<u> </u>	1973	30
	Employee smoking history	χ	<u> </u>	1987	30
	Accident history	<u>Y</u>	×	1973	54 RS
	Retirement date	<u> </u>	<u> </u>	1973	10405
	Termination date		``	1973	10
	Vital status of retirees	<u>k</u>	×	1973 (CO 1900!	S) SURVIVORS BENEFIC
	Cause of death data	<u> </u>	<u> </u>	1973 (0 1970)	FOREVER
				•	

* OPERATION STARTED IN 1977 (SOME EMPLOYEES HIPED IN 1973)

[_] Mark (X) this box if you attach a continuation	sheet
--	-------

_]	a.	b.	c.	d.	e.
			Yearly	Total	Total
	Activity	Process Category	Quantity (kg)	Workers	Worker-He
	Manufacture of the listed substance	Enclosed	<u> </u>		
		Controlled Release	N/A		
		0pen	WA-		
	On-site use as	Enclosed	<u> </u>		
	reactant	Controlled Release	672009	15	22,0
		0pen	_N/A		
	On-site use as	Enclosed	N/A		
	nonreactant	Controlled Release	NA		
		0pen	NA		
	On-site preparation	Enclosed	MA		
	of products	Controlled Release	N/A		
		0pen	NA		

9.03 CBI	Provide a descriptive encompasses workers wh listed substance.	job title for each labor category at your facility that o may potentially come in contact with or be exposed to the
 -		
[_]		
	Labor Category	Descriptive Job Title
	A	FOAM COUTROL PERSON (DOORS)
	В	RELIEF OPERATORS (NORMAL PRODUCTION OPERATOR
	С	FOAM CONTROL PERSON (CASE)
	D	PROCESS CONTROL ENGINEERS
	E	STATION ATTENDANTS
	F	DEV. ENGINEERS
	G	ADV. Mfg. ENGINEERS OR Mfg ENG
	Н	MATERIAL HANDLERS
	I	INDUSTRIAL HYGIENISTS
	J	SAFETY/ENVIRONMENTAL ENGINEERS
		7

 $[\overline{\times}]$ Mark (X) this box if you attach a continuation sheet.

W 113	Provide a descriptiv	e job title for each labor category at your facility that
9.03	encompasses workers listed substance.	who may potentially come in contact with or be exposed to the
CBI		
[_]		
	Labor Category	Descriptive Job Title
	A	SECURITY PERSONNEL
	В- (QC LAB TECHNICIAN
	c -	QC INSPECTORS
	D ·	QC Engineers
	E / V	MAINTENANCE
	F	
	G	
	н	
	I	
	J	
	Mark (V) this have if	you attach a continuation sheet.

9.04	In accordance with the instructions, indicate associated work areas.	provide	your	process	block	flow	diagram(s)	and
<u>CBI</u>								
,,	Process type							

SEE ATTACHED FLOW CHARTS OF 42A AND 42B (ATTACHED UNDER WEATH)

WORK AREA I = PROCESS 7.01A (FOAM BULK CHEMICAL
SYSTEMS) P 42A


WORK AREA 2 = DOOR POUR STATION 7.41 (701B PROCESS
P. 42B)


WORK AREA 3 = CASE POUR STATIONS 7.59 (7.01B PROCESS
P. 42B)

WORK AREA 4 = ALL OTHER (FOAM DECK OR
METERING DECK)

THIS IS IDENTIFIED ON PROCESS 7.01B,
P. 42B AS
7 R + hrough 7.39
7EE THROUGH 7.47
7 R TO 7 TTT
7EE TO 7 DDDD

 $^{[\}overline{X}]$ Mark (X) this box if you attach a continuation sheet.





.n.t	additional areas not	in contact with or be exposed to the listed substance. Add any shown in the process block flow diagram in question 7.01 or question and complete it separately for each process type.
BI		7.01 A FORM BULK CHEMICAL OYSTEMS
l	Process type	7.018 CAS, E/DOOR FOAM SYSTEM
	Work Area ID	Description of Work Areas and Worker Activities
	1	BULK CHENICAL UNLOADING, STORAGE, FILTERING. INVOLUES BLEWDING OF COMPONENT "B" BE MASTERBATCH
	2	DOORS ARE FORMED AT THE DOOR POUR STATION. WORKERS
	3	CASES ARE FORMED. WORKERS ATTEND CASE TOAM STATIONS, MONTOR OPERATIONS - CHANGE PANELS, FIXTURES, FORM HEADS, ECT
	4	FOAM METERING OPERATIONS - MATERIALS ARE STORED, FILTERS AND DELIVERED TO USE SYSTEMS. TOTAL SYSTEM
	5	MONITORS FROM THIS AREA. CALIBRATIONS PERFORMED HERE. ALL MAINTENANCE DONE HERE.
	6	
	7	
	8	
	9	
	10	

9.06 CBI	each labor of come in conf	category at you tact with or be	ble for each work area or facility that encome e exposed to the liste y for each process typ	passes worker d substance.	s who may pot Photocopy th	entially
[_]	Process type	e <u>7.</u>	OIA FOAM Bulk C	HEMICALS		
	Work area	• • • • • • • • • • • • • •		1		
	Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Number of Days per Year Exposed
	<u> </u>	4	Skin/INHALATION	OLIGC	A	191
	D	4	INHALATTON	<u>GC</u>	A	191
	F	3	3km/INHALATION	OL/BC	A	50 851
	<u>_</u> G		3km/INHALATION	OLIGO	A	191
	<u>H</u>	4	SKIN/INAALATION	OLIGE	A	24
	I		3KIN/INHALATTON	ol/GC	A	52_
			3KIN/INHAL ATTON	OL/6C	A	52_
	<u> A-(</u>	3	INHALATION	<u>GC</u>	A	365
			SKIN/INHALATION	0460	A	191
	E·1	50	SKIN/INHALATION	OLIGE	A	191
	the point of GC = Gas (tempe GU = Gas (tempe inclu SO = Solid 2 Use the fol A = 15 minu	of exposure: (condensible at erature and precure and precure and precure and precure fumes, variations)	essure) AL = at ambient OL = essure; IL = cors, etc.) to designate average l	Sludge or sl Aqueous liqu Organic liqu Immiscible l (specify pha 90% water, 1	urry id id iquid ses, e.g., 0% toluene) sure per day: 2 hours, but	
	exceedi C = Greater	ing 1 hour than one hour ng 2 hours	E = C, but not		4 hours, but ours	not

[_] Mark (X) this box if you attach a continuation sheet.

per of s per ear posed
s per ear oosed
1
1
1
085
2/
+
52_
52
ı
11

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

•	-	y for each process typ OIB CASE/DOD	_		
			3		
Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Numbe Days Yea Expo
C	4	SHIN/INHALATION	01/60		191
£		SKIN/INHALATION	04/60	E	191
2	4	INHALATION	GC	A	191
G		Sky/INHALATION	01/60	B	19
_H	_4	shm/Inhalktion	OHEC	<u>A</u>	24
_ I _		Shin/IN HALFTION	01/60	A	
<u>J</u>		SKIN/INHALATION	01/60	4	_57
<u>A·1</u>	_3	INHALATION	<u> </u>	<u> </u>	36
<u>C.1</u>	_2	SKIN/INHALATION	04/60	<u>A</u>	[9]
<u>D. 1</u>		SKIN INHALATION	OL/GC	<u>A</u>	57
<u> </u>	50				1 <i>3</i> 1
	of exposure:	to designate the physi	cal state of	the listed su	ostance
tem GU = Gas tem inc	c (condensible amperature and pros s (uncondensible s perature and pros cludes fumes, va	essure) AL = at ambient OL = essure; IL =	Sludge or sl Aqueous liqu Organic liqu Immiscible l (specify pha	aid aid iquid ases, e.g.,	
S0 = Sol			90% water, 1	·	
		to designate average l			
B = Great excee	nutes or less er than 15 minut ding 1 hour	tes, but not $E = 0$	exceeding 4 h Greater than	4 hours, but i	
C = Great	er than one hour	, but not	exceeding 8 h	ours	

] Process t	ype <u>7</u>	1.01 B C45E/ DOO	r foun	SYSTEM	1988
Work area				4	
Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day ²	Number of Days per Year Exposed
<u> </u>	2	SKIN/INHALATION	04/60	A	191
C	K	SKN/WHALATION	OLIGE	A	191
	4	INH4 LATION	GC_	<u> </u>	191
6		skiu/in4447700	OL/GC	A	191
_H	4	skin/ whaterion	04/60	A	
1		Skin/ INHALATION	01/60	4	
<u> </u>		SK-W/INHALATION	OL/GC	4	52
<u>A·1</u>	3	INHALATION .	GC		365
B .		Skin/tullalation	OL/GC	4	52
<u> </u>	<u>z</u> 50	SKIN INHALATION SKIN INHALATION	OLIGE	4	191
the point GC = Gas ten GU = Gas ten inc SO = Sol ² Use the f	of exposure: (condensible and prosecution of the condensible appearature and prosecution of the condensible and appearature and appeara	essure) AL = at ambient OL = essure; IL = pors, etc.) to designate average 1 D = essure	Sludge or si Aqueous liqu Organic liqu Immiscible i (specify pha 90% water, i	lurry uid uid liquid ases, e.g., l0% toluene) osure per day:	

	Photocopy this quest:	A) exposure levels and the 15-min ion and complete it separately for	or each process type and work
CBI		7.01 A FORM BULK	Chemical Systems
[_]	Process type	7.01B CASE/DOOR FO	dam Jystems
	Work area		ALL
	Labor Category	8-hour TWA Exposure Level (ppm, mg/m ³ , other-specify)	15-Minute Peak Exposure Level (ppm, mg/m³, other-specify)
	ALL	20.005 ppm	Generally 40.02 pp
	-		

9.08 CBI	If you monitor worke	r exposur	e to the lis	sted substai	nce, compl	ete the fo	llowing table.
[_]	Sample/Test	Work Area ID	Testing Frequency (per year)	Number of Samples (per test)	Who Samples ¹	Analyzed In-House (Y/N)	Number of Years Records Maintained
	Personal breathing zone	2,3,4	HONE	1	NC	N	30+
	General work area (air)	ALL	Continual	CONTINUO	s A ,	<u> </u>	30+
	Wipe samples Adhesive patches Blood samples Urine samples Respiratory samples Allergy tests Other (specify)		AS NEEAC				30
	Other (specify)	<u></u>		mended			
	Other (specify)	<u>ML</u>		3	D	_ y	30
	¹ Use the following c A = Plant industria B = Insurance carri C = OSHA consultant D = Other (specify)	l hygieni er /		takes the	monitorin	g samples:	

[_]	Sample Type	Sa	mpling and Analyt	ical Methodolo	gy Wallan Extractle
	PERSONAL	INTEGRATED / 11	MPINGER /NITRO	REAGENT/ KI	LIQUID CHROMATO
	CONTIPLOUS	MD4 7005/710	O photo offic	(REFLECTANCE PAPER TAPE	e/Coloe, MeTric
	RAST	Bloca AUTIGE	N /RAST AUTIB	ODY PITER	
	PFT	N PARAMA	ters - Includ	DES MUVOI	J
		Emergency	RESPONDER5		
9.10 CBI	If you conduct perso specify the followin				ubstance,
[<u> </u>	Equipment Type ¹	Detection Limit ²	Manufacturer	Averaging Time (hr)	Model Number
	D (IMPINGER)	EST 0.005 A	VAC1005	0.25	NA
-	H CONTINUOUS	20.005 A	MDA	18 m. N (5T	in 7005/7100
		-			
					-
	1				
	¹ Use the following c A = Passive dosimet		ersonal air monito	oring equipmen	t types:
	B = Detector tube C = Charcoal filtra D = Other (specify)				
	Use the following co	odes to designate an	nbient air monitor	ing equipment	types:
	E = Stationary moni F = Stationary moni				
	G = Stationary moni H = Mobile monitori	tors located at plar	nt boundary		
	I = Other (specify)				
	² Use the following c	odes to designate de	etection limit uni	ts:	
	A = ppm B = Fibers/cubic ce C = Micrograms/cubi				

[_]	Test Description	Frequency (weekly, monthly, yearly, etc.)
	PHLMONARY FUNCTION	PEZPLACEMENT, AFTER GMONT
		ON JOB Z TOI; ANNUAlly
		THEREAFTER · Also After
		EXPOSURE/COMPLAINT/
		Referent.

Describe the engineering cont to the listed substance. Pho	tocopy this	s question and comp	lete it separat	ker expo ely for
process type and work area.	7.01 A	FORM BULK CHE	imicals	
Process type	7.013	BASE/DOOR FOAM	M SYSTEM	
Work area	ALL.		1, 2, 3	3, 4
Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Yea Upgra
Ventilation:				•
Local exhaust	<u>y</u>	1976		1983
General dilution				
Other (specify)				
PROCESS ISOLATION	<u> </u>	1987		
Vessel emission controls	<u> </u>	1988		
Mechanical loading or packaging equipment				
Other (specify)	~			ujenė <u>uu</u> ,

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

9.13 <u>CBI</u>	Describe all equipment or process modifications you have a prior to the reporting year that have resulted in a reduct the listed substance. For each equipment or process modification the percentage reduction in exposure that resulted. Photocomplete it separately for each process type and work area 7.01 A FORM BULK CHEMIN	tion of worker exposure to fication described, state ocopy this question and
[-]	Process type 1.01B CASE/DOOR FOAM	SYSTEM
	Work area	ALL 1, 2, 3, 4
	Equipment or Process Modification	Reduction in Worker Exposure Per Year (%)
	ALL ISOCYANATE USE STORAGE AREAS WERE	90% of workers
	ENCLOSED (TOTALLY) ISOLATING FORM PROCESSES	POTENTIAL ENPOSURE
	FROM REMAINDER OF FACTORY. VENTILATION ENCLOSURE	& ELIMINAT
	WITHIN ENCLOSURES WERE WSTALLED. ISOLATION	
	PROCESS (-) PRESSURE AND INDIVIDUAL VENTICATION	
	SYSTEM ALARMS WELL INSTALLED (1987)	
	7.01B INSTALLED CLOSED LOOP CALIBRATION SYSTEM	100% EliminaTion
	CALIBRATION SYSTEM	of Exposure During
		CALIBRATION: 100%
		ELIMINATION OF WASTE
		CALIBRATION FOLOM

PART 9.14 CBI	Describe the persona in each work area in	e AND SAFETY EQUIPMENT I protective and safety order to reduce or elicy this question and com 7.01 A FOAW	ninate to plete it BULK	their exposes separate	sure to the ly for each	listed process type
[_]	Process type	. 7.01B CASE/	DOOR	FOAM	JYSTEM	
	Work area				<u>All</u>	1,2,3,4
		Equipment Types Respirators Safety goggles/glasses Face shields Coveralls Bib aprons Chemical-resistant glo Other (specify) BooTs/ BooTles	- - - -	Wear or Use (Y/N) / / / / / / / / / / / / /		

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

	tested, and the type and f complete it separately for		s type.		temical	
<u>CBI</u>	Dungan tung			•	W 545TEA	
l1	Process type	1 9 1	UNUA 100	Fit	10 413 (21)	Frequency of
	Work Respirato Area Type	r	Average Usage ¹	Tested (Y/N)	Type of Fit Test ²	Fit Tests (per year)
	1 +P Avelive Suppli	en or SCBA	C	<u> </u>	QL	Lenknown
	2 +P Airline Suppli	en or SCBA	<u> B</u>	<u> </u>	<u>QC</u>	unknown
	3 to Air live Suppli	eo or SCBA	<u>B</u>	<u> </u>	<u>QL</u>	CENTRALINA
	4 to AIR INE Supple	es or SCBA	_B_	<u> </u>	QL	UNKNOWN
	E = Other (specify) Use the following codes t QL = Qualitative QT = Quantitative	o designate	the type o	f fit tes	::	
		* Should	be p	er/us-e	/	

9.19 CBI	Describe all of the work preliminate worker exposure authorized workers, mark amonitoring practices, proviquestion and complete it se	to the listed su reas with warnin ide worker train	bstance (e.g., g signs, insur ing programs,	, restrict en re worker det etc.). Phot	trance only to ection and ocopy this
		A FOAM BULL			
[<u></u>]	Process type 7.00	B CASE/ DOOR	FORM SYSTE	M25	
	Work area			ALL 1,7	2, 3, 4
	RESTRICTED ENTRY, PO		•	•	,
	MOUTTORING OF WORK				
	150 CYANATES OPEN CUP CA				
	RESPURATOR (+P) AND	FULL SUTT UP L	here "Po	TENTIAL" IS	50 CYANATE
	EXPOSURE EXISTS; PROP	LIBIT EXPOSURE	TO THUSE A	T HIGH RISK	UIA MEDICAL SCREE
9.20	Indicate (X) how often you leaks or spills of the lisseparately for each process	ted substance.	Photocopy this	s question an	d complete it
	Process type 7.6 Work area	1 A Paocess	-Foan Bulk	2 Chemicals	17.01B FORM SYS
		Less Than Once Per Day	1-2 Times Per Day	3-4 Times Per Day	More Than 4 Times Per Day
	Work area	Less Than		3-4 Times	More Than 4
	Work area Housekeeping Tasks	Less Than		3-4 Times	More Than 4
	Work area Housekeeping Tasks Sweeping	Less Than Once Per Day		3-4 Times	More Than 4
	Work area Housekeeping Tasks Sweeping Vacuuming	Less Than Once Per Day		3-4 Times	More Than 4
	Work area Housekeeping Tasks Sweeping Vacuuming Water flushing of floors	Less Than Once Per Day		3-4 Times Per Day	More Than 4

<u> </u>	
9.21	Do you have a written medical action plan for responding to routine or emergency exposure to the listed substance?
	Routine exposure
	Yes
	No 2
	Emergency exposure
	Yes
	No
	If yes, where are copies of the plan maintained?
	Routine exposure: PLANT DISPENSARY
	Emergency exposure: Plant Dispension
9.22	Do you have a written leak and spill cleanup plan that addresses the listed substance? Circle the appropriate response.
	Yes
	No 2
	If yes, where are copies of the plan maintained? THROUGHOUT PLANT
	Has this plan been coordinated with state or local government response organizations? Circle the appropriate response.
	Yes
	No 2
9.23	Who is responsible for monitoring worker safety at your facility? Circle the appropriate response.
	Plant safety specialist
	Insurance carrier 2
	OSHA consultant
	Other (specify) SZPARTMENTAL SAFETY REAS AND TEAM LEADERS
[_}	Mark (X) this box if you attach a continuation sheet.

SECTION 10 ENVIRONMENTAL RELEASE

General Instructions:

Complete Part E (questions 10.23-10.35) for each non-routine release involving the listed substance that occurred during the reporting year. Report on all releases that are equal to or greater than the listed substance's reportable quantity value, RQ, unless the release is federally permitted as defined in 42 U.S.C. 9601, or is specifically excluded under the definition of release as defined in 40 CFR 302.3(22). Reportable quantities are codified in 40 CFR Part 302. If the listed substance is not a hazardous substance under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and, thus, does not have an RQ, then report releases that exceed 2,270 kg. If such a substance however, is designated as a CERCLA hazardous substance, then report those releases that are equal to or greater than the RQ. The facility may have answered these questions or similar questions under the Agency's Accidental Release Information Program and may already have this information readily available. Assign a number to each release and use this number throughout this part to identify the release. Releases over more than a 24-hour period are not single releases, i.e., the release of a chemical substance equal to or greater than an RQ must be reported as a separate release for each 24-hour period the release exceeds the RQ.

For questions 10.25-10.35, answer the questions for each release identified in question 10.23. Photocopy these questions and complete them separately for each release.

10.01	Where is your facility located? Circle all appropriate responses.
<u>CBI</u>	
[_]	Industrial area
	Urban area
	Residential area
	Agricultural area
	Rural area
	Adjacent to a park or a recreational areaVIRTUAUX
	Rural area
	Within 1 mile of a school, university, hospital, or nursing home facility
	Within 1 mile of a non-navigable waterway
	Other (specify)10
<u></u>	Mark (X) this box if you attach a continuation sheet.

	Specify the exact location of you is located) in terms of latitude (UTM) coordinates.			
	Latitude		<u>343</u> .	50, 30
	Longitude		084.	56, 45
	UTM coordinates Zone	e, North	ning, Ea	asting
10.03	If you monitor meteorological con the following information.	nditions in the vicin	nity of your fact	ility, provide
	Average annual precipitation			inches/year
	Predominant wind direction			
10.04	Indicate the depth to groundwater	below your facility	7.	
	Depth to groundwater			meters
10.05 CBI	For each on-site activity listed, listed substance to the environme Y, N, and NA.)	indicate (Y/N/NA) ant. (Refer to the i	all routine relea	ases of the a definition of
	listed substance to the environme Y, N, and NA.)	nt. (Refer to the i	nstructions for rironmental Relea	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity	nt. (Refer to the i	rironmental Relea	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing	nt. (Refer to the i	rironmental Release	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing	nt. (Refer to the i	rironmental Relea	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing Processing	nt. (Refer to the i	rironmental Release	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing	nt. (Refer to the i	rironmental Release	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing Processing	nt. (Refer to the i	rironmental Release	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used	nt. (Refer to the i	rironmental Release	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage	Env. Air Air N/A N/A N/A	rironmental Release	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	Env. Air Air N/A N/A N/A	rironmental Release	a definition of
<u>CBI</u>	listed substance to the environme Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	Env. Air Air N/A N/A N/A	rironmental Release	a definition of

	Provide the following information for the liste of precision for each item. (Refer to the inst an example.)		
CBI	1.00		
[_]	Quantity discharged to the air	34	kg/yr <u>+</u> <u>10</u> %
	Quantity discharged in wastewaters	w/4	kg/yr ± %
	Quantity managed as other waste in on-site treatment, storage, or disposal units	5460	kg/yr ± 1 2
	Quantity managed as other waste in off-site treatment, storage, or disposal units	5460	kg/yr <u>+</u> %
		-	

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

10.08 <u>CBI</u>	for each process stre process block or resi and complete it separ	technologies used to minimize release of tam containing the listed substance as idendual treatment block flow diagram(s). Phoately for each process type. 7.01 A FOAM BUIL CHEMICAL SYSTE	tified in your tocopy this question
1 J	Trocess type	THE MAN SOUTH STATE OF THE STAT	ru
	Stream ID Code	Control Technology	Percent Efficiency
	7 M	DRY SCRUBBER (ABSORBER)	290%
	7I	NONE	N/A
	7P	NONE	N/A

[X] Mark (X) this box if you attach a continuation sheet.

10.08 Describe the control technologies used to minimize release of the listed substance for each process stream containing the listed substance as identified in your process block or residual treatment block flow diagram(s). Photocopy this question and complete it separately for each process type.

[__] Process type 7.018 CASE DOOR FORM SYSTEM

Process type	7.018 CASE/ DOOR FORM	345TEM
Stream ID Code	Control Technology	Percent Efficiency
7.QQ	NONE	N/A
7.44	NONE	MA
7. WW	NONE	N/A
7.77	NONE	N/L
7. JJJ	NONZ	MA
7. NUN	NONE	NIA
7.000	NONE	NA
7. 444	NONE	N/A
7. <i>EEEE</i>	NONE	N/A
7. BBB	None	N/A

^[] Mark (X) this box if you attach a continuation sheet.

PART B RELEASE TO AIR 10.09 Point Source Emissions -- Identify each emission point source containing the listed substance in terms of a Stream ID Code as identified in your process block or residual treatment block flow diagram(s), and provide a description of each point CBI source. Do not include raw material and product storage vents, or fugitive emission []sources (e.g., equipment leaks). Photocopy this question and complete it separately for each process type. FORM BULK CHEMICAL SYSTEM 7.014 7.01B CASE / book FOAM SYSTEM Process type Point Source ID Code Description of Emission Point Source LINLOADING PUMP + FILTER USAIS 7.I 7.P RECIPCULATION FILTER VENTS 7.44 DOOR LINE FILTER UZNI (ON FORM DECLE 7.WW 900A POUR STATION FILTER VENT 7. ZZ (METERING POMP) VENI 7. BBB DOOR POUR STATION USET 7. NN N CASE LINE FILTER VENT 7.000 METERING PUMP STAND VENI 7.404 CALIBRATION STAND VENT CASE FORM SYSTEMS (POUR) VENTS 1.EEEE

* EMERGENCY VENT FOR METERING DECK NOT Shown

11	Mark	(X)	thic	hov	if vo	u attach	a	continuation	sheet
ıı	nark	(Δ)	tiiis	DOX	II yo	u attacii	a	Continuation	sneet.

Mark

8

this

xod

10.10 Emission 10.09 by CBI	n Characte v completi	ristics — — Ch ng the followi	aracterize the	emissions:	for each Point N 1988	Source ID Co	de identified Maximum	
Point						Maximum	Emission	Maximum Emission
[_] Source ID	Physical	Average	n 2	3	Average	Emission	Rate	Rate
Code	State	Emissions (kg/day)	Frequency ² (days/yr)	Duration ³ (min/day)	Emission Footor	Rate	Frequency	Duration
		(16/02)	(days/yr)		Factor*	(kg/min)	(events/yr)	(min/event)
T	<u>~</u> }		191	960	1.27×10	WKNOWN	WALLACUM	KUMCHOWN
79	<u></u>		191	960	1.27 × 10	UNKNOWN	unknown	unlyone
744			191	960	1.17×10-5	WKINON	WILLIAM	MAKATUN
7 WW	<u> </u>		191	960	27×10-5	wkinod	UN PAPUN	unknown
722	<u> </u>	0.176	191	460	2.27 × 10 -5		unkarrow	UNKNOON
7888	<u> </u>	, <u> </u>	191	960	2.27×10-5	UNKNOWN	MILANN	ANKADIN
JUNA	V		191	960	2.27×10-5	WAKNOWN	unknown	UNKURUN
7000	V		191	460	8.27×10-5	1	CAN L-NORW	unknown
71111	~		19/	960	2.77×10	1		1. ,
7.86	7		191	960	2.27×10-5	WALL OF THE STREET	while some	MKNOW
			121	100	/ FIA	WILL MOTON	WILMIN	MARTIOTA

¹Use the following codes to designate physical state at the point of release: G = Gas; V = Vapor; P = Particulate; A = Aerosol; O = Other (specify)

* Max Emission RATE NOT Appearably Sifferent FROM AU EMISSION RATE. EVENTS & 1/42

²Frequency of emission at any level of emission

³Duration of emission at any level of emission

 $^{^4}$ Average Emission Factor — Provide estimated (\pm 25 percent) emission factor (kg of emission per kg of production of listed substance)

10.11 Stack Parameters -- Identify the stack parameters for each Point Source ID Code identified in question 10.09 by completing the following table.

[_]	Point Source ID Code	Stack Height(m)	Stack Inner Diameter (at outlet) (m)	Exhaust Temperature (°C)	Emission Exit Velocity (m/sec)	Building Height(m)	Building Width(m) ²	Vent Type ³
	7x	10-6	3.7	26	421	N/A	-W/A	✓
	7P	<u>_10.b_</u>	3.7	w_	421	NA	MA	V
	7uu	11.3	3.7	16_	_2	N/A	MA	<u> </u>
	TWW	11.3	3.7	26	6.1	NA	NA	V
	722	11.3	3.7	26	6.0	NA	NA	✓
	786B	11.3	3.7	<u>Hb</u>	8.7.	NA	NA	√
	TNUN	11.3	3.7	26	18.6	NIN	N/A	✓
	7000	11.3	3.7	16	7.8	N/4	NA	<u> </u>
	7444	11.3	3.7	26	6.9	NA	NA	√
	1eek	113	<u>3.7</u>	26	15.9	NA	NA	
				-		,		


¹Height of attached or adjacent building

H = Horizontal

V = Vertical

²Width of attached or adjacent building

³Use the following codes to designate vent type:



10.13	Equipment Leaks Complete types listed which are expo according to the specified the component. Do this for residual treatment block fl not exposed to the listed s process, give an overall pe	sed to the leading to the lead perces ow diagram(substance. I	isted substant of the stype ion. Do not find this is	bstance a e listed dentified ot includ s a batch	nd which a substance in your p e equipmen or intern	are in ser passing process b nt types mittently	rvice through lock or that are operated
<u>CBI</u>	exposed to the listed subst for each process type.	ance. Photo	copy this	s questio	n and com	plete it s /	separately N
[_]	Process type 7.0	DIA FOAM Y	suls Ch	emests	AND 7.015	3 DOUB/CA	se toam :
	Percentage of time per year type						rocess
					Service by ce in Proc		am
	Equipment Type Pump seals ¹	Less than 5%	5-10%	11-25%	26-75%	76-99%	Greater than 99%
	Packed	N/A.	NA	2/2	/ _	Ma	NA
	Mechanical	17/D	NA	nla			
	Double mechanical ²		MA		11	1/2	
	Compressor seals ¹	1// ()	1/10	Wla	NIM	n/A	No
	Flanges	1/10	NA	NA	HUKNOWA	A/A	NA
	Valves		- 11-14-		· Serting M		— <i>N</i> / <i>N</i> —
	Gas ³	N/A	N/A	N/a	N/A.	N/A	NK
	Liquid		NA	NA	50851	10/14	MA
	Pressure relief devices ⁴ (Gas or vapor only)		NA	NA	4-	n/A	NA
	Sample connections	1	a	ı)	1	,	1
	Gas	<u> W</u> A	NA	N/R	N/m	NA	Mr
	Liquid	MA	NA	NA	_i/so_	MA	NA
	Open-ended lines ⁵ (e.g., purge, vent)	· {	,	{	,	-/	//.
	Gas	N/a	NA	NA	NA	NA	
	Liquid	W/A	$\underline{N}^{\prime}\underline{F}$	NX	MA	MA	Ma
	¹ List the number of pump and compressors	l compressor	seals, r	ather tha	in the num	ber of pu	mps or
10.13	continued on next page						

10.13	(continued)								
	² If double mechanical seals are operated with the barrier (B) fluid at a pressure greater than the pump stuffing box pressure and/or equipped with a sensor (S) that will detect failure of the seal system, the barrier fluid system, or both, indicate with a "B" and/or an "S", respectively ³ Conditions existing in the valve during normal operation								
	⁴ Report all pressure relief devices in service, including those equipped with control devices								
	$^5\mathrm{Lines}$ closed during normal operation that would be used during maintenance operations								
10.14 <u>CBI</u>	Pressure Relief Devices with pressure relief devices in devices in service are contenter "None" under column	dentified in 10.13 to ntrolled. If a press	o indicate which pr	ressure relief					
[]	a.	b.	c.	d.					
	Number of Pressure Relief Devices	Percent Chemical in Vessel	Control Device	Estimated Control Efficiency ²					
	4		NONE	100					
		-							
	Refer to the table in question 10.13 and record the percent range given under the heading entitled "Number of Components in Service by Weight Percent of Listed Substance" (e.g., <5%, 5-10%, 11-25%, etc.)								
:	with rupture discs under n	The EPA assigns a control efficiency of 100 percent for equipment leaks controlled with rupture discs under normal operating conditions. The EPA assigns a control efficiency of 98 percent for emissions routed to a flare under normal operating							
	Mark (X) this box if you at	tach a continuation	sheet.						

Process type	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • •	7.01A FOR	m Bulk C	hences 3
	Leak Detection	_	7.01B CAS	SE/DOUR FO	AM Syst
	Concentration (ppm or mg/m³) Measured at		Frequency of Leak	Repairs Initiated	Repairs Complete
Equipment Type	Inches from Source	Detection Device ¹		(days after detection)	(days aft
Pump seals	1	,		D	
Packed	WA	N/A	N/N	NA	N/A
Mechanical	NA	N/A	NA	MA	N/A
Double mechanical	VARIFAD	FPM	CONTINUOUS	4	4
Compressor seals	NA	N/H	N/h	N/A	N/A
Flanges	VARIGO	FPM	NIT	N/A	NIF
Valves	,				1
Gas	N/A	NA	N/A	N/A	NA
Liquid	VARGO	FPM	CONTINUOUS	N/A	N/V
Pressure relief devices (gas or vapor only)	4	FPM	CONTINUOUS	د ا	۷.
Sample connections	,		,	1	1
Gas	N/A	N/A	Mr	NA	-NA
Liquid	N/A	NA	_WA	1/1	A L
Open-ended lines		η,	0	/.	Λ
Gas	N/X	NA	Nh	- W/A	Ny
Liquid	N) /A	NYA	1/8	N/#	NA

	Mark	10.16 <u>CBI</u>	Raw Material, Intermediate and Product Storage Emissions – Complete the following table by providing the information on each liquid raw material, intermediate, and product storage vessel containing the listed substance as identified in your process block or residual treatment block flow diagram(s). Operat-
	rk (X) thi		Vessel Vessel ing Floating Composition Throughput Filling Filling Inner Vessel Vessel Vessel Design Vent Control Basis Vessel Roof of Stored (liters Rate Duration Diameter Height Volume Emission Flow Diameter Efficiency for Type Seals Materials per year) (gpm) (min) (m) (m) (l) Controls Rate (cm) (%) Estimate
	CO	7.3	F N/A 60 527,908 17 6 240 1.4 3 22,700 DRY ATMOS 10 >90 C
i	box i	7.30	F N/A 60 363, 69655 17 254 30 1.8 1 1892 NONE ATMOS 10 N/A N/A
:	f you	7.48	F N/A 60 17421785 17 85 60 1.5 .9 3785 NONE ATMOS · 10 N/A N/H
	u at		
	tach		
	a c		
120	ontinuat		¹ Use the following codes to designate vessel type: ² Use the following codes to designate floating roof seals:
	ion	1 1 1	F = Fixed roof MS1 = Mechanical shoe, primary
	shee		CIF = Contact internal floating roof MS2 = Shoe-mounted secondary NCIF = Noncontact internal floating roof MS2R = Rim-mounted, secondary
	et.		EFR = External floating roof P = Pressure vessel (indicate pressure rating) LM1 = Liquid-mounted resilient filled seal, primary LM2 = Rim-mounted shield
			H = Horizontal U = Underground VM1 = Vapor mounted resilient filled seal, primary VM2 = Rim—mounted secondary VMW = Weather shield
			³ Indicate weight percent of the listed substance. Include the total volatile organic content in parenthesis
			⁴ Other than floating roofs
			⁵ Gas/vapor flow rate the emission control device was designed to handle (specify flow rate units)
			⁶ Use the following codes to designate basis for estimate of control efficiency:
			C = Calculations S = Sampling

PART E NON-ROUTINE RELEASES

10.23 Indicate the date and time when the release occurred and when the release ceased or was stopped. If there were more than six releases, attach a continuation sheet and list all releases.

Release	Date Started	Time (am/pm)	Date Stopped	Time (am/pm)
	-		/	/
_2				
3				
4				
5			/	
6		/	/	

10.24 Specify the weather conditions at the time of each release.

Release	Wind Speed (km/hr)	Wind Direction	fumidity (%)	Temperature (°C)	Precipitation (Y/N)
Mercase	(1011/112)	<u>DITECTION</u>	/ \(\frac{\(\lambda_0\)}{\}		
1					
2					
3				·	
4		/			
5					
6					
	/				

[] Mark (X) this box if you attach a continuation sheet.

APPENDIX I: List of Continuation Sheets

Attach continuation sheets for sections of this form and optional information after this page. In column 1, clearly identify the continuation sheet by listing the question number to which it relates. In column 2, enter the inclusive page numbers of the continuation sheet for each question number.

Continuation

Question Number	Sheet Page Numbers
(1)	(2)
7.0	42A
7.0	42B
7.03	44A
7.04	45 A
7.04	<u>45 B</u>
1.04	45 C
1.04	45 1
7.04	15 2
7.04	45 F
7.04	456
7.04	<u>45 K</u>
7.05-	46A
7.05	46 B
7.06	47A
7.06	47 B
7.06	41 C
7.06	47 D
8.05	54 A
9.03	90 A

[X] Mark (X) this box if you attach a continuation sheet.

APPENDIX I: List of Continuation Sheets

Attach continuation sheets for sections of this form and optional information after this page. In column 1, clearly identify the continuation sheet by listing the question number to which it relates. In column 2, enter the inclusive page numbers of the continuation sheet for each question number.

	Continuation
Question Number	Sheet Page Numbers
(1)	(2)
90.4	42A
	42B
9.06	93 A
	93 B
	93 C
10.08	112A
CONTINUATION PASE	
V	

Mark (X) this box if you attach a continuation s	



DOW CHEMICAL U.S.A.

January 25, 1989

MIDLAND, MICHIGAN 48674

GENERAL ELECTRIC CO HOME REF DEPT 5528286

8TH ST S E DECATUR

AL 35601

Sir/Madam:

Enclosed are Material Safety Data Sheet(s) which provide information on products which you have purchased from us in the recent past. Since you may redirect the products to more than one place within your location, please make sure this information is available to all persons handling and/or using the product.

These Material Safety Data Sheet(s) have either been revised since you last received them or are for products which you recently purchased. Please consider them as the current copy to replace any previous version you may have received.

The distribution of these sheets is part of a continuing program of providing information and updating our customers. The regulations promulgated by OSHA for Hazard Communication, 29 CFR 1910.1200 have been considered in preparing these Material Safety Data Sheet(s).

Thank you for your help.

J.E. Betso Health and Environmental Sciences 1803 Building

klr

Enclosure(s)

BOUNT OF THE STATE OF THE STATE



Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92066

Page: 1

PRODUCT NAME: VORANATE (R) 3071 ISOCYANATE

Effective Date: 12/27/88 Date Printed: 01/25/89 MSDS:001138

INGREDIENTS: (% w/w, unless otherwise noted)

60% CAS# 026471-62-5 Toluene Diisocyanate (TDI) Prepolymer of TDI and propoxylated CAS# 039279-01-1 10-30% glycerine Prepolymer of TDI and propoxylated 10-30% CAS# 059154-64-2 sucrose

This document is prepared pursuant to the OSHA Hazard Communication Standard (29 CFR 1910.1200). In addition, other substances not 'Hazardous' per this OSHA Standard may be listed. Where proprietary ingredient shows, the identity may be made available as provided in this standard.

2. PHYSICAL DATA:

BOILING POINT: 480F, 249C VAP PRESS: .04 mmHg @ 75F, 24C

VAP DENSITY: 6.00 SOL. IN WATER: Reacts

SP. GRAVITY: Approx. 1.27 @ 25/40 APPEARANCE: Clear brown liquid ODOR: Very sharp, pungent odor.

3. FIRE AND EXPLOSION HAZARD DATA:

FLASH POINT: 260F, 127C METHOD USED: PMCC, ASTM D93

FLAMMABLE LIMITS LfL: Not determined UFL: Not determined

EXTINGUISHING MEDIA: Carbon dioxide, dry chemical, or foam. If water is used, it should be in very large quantity. The reaction between water and hot isocyanate may be vigorous.

(Continued on Page 2)

(R) Indicates a Trademark of The Dow Chemical Company

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92066

Page: 2

PRODUCT NAME: VORANATE (R) 3071 ISOCYANATE

Effective Date: 12/27/88 Date Printed: 01/25/89

MSDS:001138

3. FIRE AND EXPLOSION HAZARD DATA: (CONTINUED)

FIRE & EXPLOSION HAZARDS: Down-wind personnel must be evacuated.

Do not reseal contaminated containers since pressure build-up
may cause rupture.

FIRE-FIGHTING EQUIPMENT: People who are fighting isocyanate fires must be protected against nitrogen oxide fumes and isocyanate vapors by wearing positive pressure self-contained breathing apparatus and full protective clothing.

4. REACTIVITY DATA:

STABILITY: (CONDITIONS TO AVOID) Stable when stored under recommended storage conditions. Store in a dry place at temperatures between 15-38C (60-100F).

INCOMPATIBILITY: (SPECIFIC MATERIALS TO AVOID) Water, acid, base, alcohols, metal compounds, surface active materials. Avoid water as it reacts to form heat, CO2 and insoluble urea. The combined effect of the CO2 and heat can produce enough pressure to rupture a closed container.

HAZARDOUS DECOMPOSITION PRODUCTS: Isocyanate vapor and mist, carbon dioxide, carbon monoxide, nitrogen oxides and traces of hydrogen cyanide.

HAZARDOUS POLYMERIZATION: May occur with incompatible reactants, especially strong bases, water or temperatures over 49C (120F).

5. ENVIRONMENTAL AND DISPOSAL INFORMATION:

ACTION TO TAKE FOR SPILLS/LEAKS:

Evacuate and ventilate spill area, dike spill to prevent entry into water system, wear full protective equipment including respiratory equipment during clean up.

(Continued on Page 3)
(R) Indicates a Trademark of The Dow Chemical Company

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92066

Page: 3

PRODUCT NAME: VORANATE (R) 3071 ISOCYANATE

Effective Date: 12/27/88 Date Printed: 01/25/89

MSDS:001138

5. ENVIRONMENTAL AND DISPOSAL INFORMATION: (CONTINUED)

Major spill: Call Dow Chemical U.S.A. (409) 238-2112. If transportation spill involved call CHEMTREC (800) 424-9300. If temporary control of isocyanate vapor is required a blanket of protein foam (available at most fire departments) may be placed over the spill. Large quantities may be pumped into closed but not sealed containers for disposal.

Minor spill: Absorb the isocyanate with sawdust or other absorbent and shovel into open top containers. Do not make pressure tight. Transport to a well-ventilated area (outside) and treat with neutralizing solution consisting of a mixture of water and 3-8% concentrated ammonium hydroxide or 5-10% sodium carbonate. Add about 10 parts of neutralizer per part of isocyanate with mixing. Allow to stand for 48 hours letting evolved carbon dioxide to escape.

Clean-up: Decontaminate floor using water/ammonia solution with 1-2% added detergent letting stand over affected area for at least 10 minutes. Cover mops and brooms used for this with plastic and dispose properly (often by incineration).

DISPOSAL METHOD: Follow all federal, state and local regulations. Liquids are usually incinerated in a proper facility. Solids are usually also incinerated or landfilled. Empty drums should be filled with water. Let drum stand unsealed for 48 hours. Before disposal drums should be drained, triple rinsed, and holed to prevent reuse. Dispose of drain and rinse fluid according to federal, state and local laws and regulations. The most commonly accepted method is in an approved wastewater treatment facility. Drums should be disposed of in accordance with federal, state and local laws and regulations. Commonly accepted methods for disposal of plastic drums are disposal in an approved landfill after shredding or incineration in an approved industrial incinerator or other appropriate incinerator facility. Steel drums are commonly disposed in an approved landfill after crushing or in accordance with other approved procedures.

⁽Continued on Page 4)

⁽R) Indicates a Trademark of The Dow Chemical Company

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92066 Page: 4

PRODUCT NAME: VORANATE (R) 3071 ISOCYANATE

Effective Date: 12/27/88 Date Printed: 01/25/89 MSDS:00.1138

6. HEALTH HAZARD DATA:

EYE: May cause pain and severe irritation with corneal injury. In animals, irritation and corneal injury healed within 21 days.

SKIN CONTACT: Prolonged or repeated exposure may cause skin irritation. Skin contact may result in allergic reaction even though it is not expected to result in absorption of amounts sufficient to cause other adverse effects.

SKIN ABSORPTION: The dermal LD50 has not been determined.

INGESTION: Single dose oral toxicity is low. The oral LD50 for rats is >4000 mg/kg. Ingestion may cause gastrointestinal irritation or ulceration.

INHALATION: Excessive vapor concentrations are attainable and could be hazardous on single exposure. Single and repeated excessive exposure may cause severe irritation to upper respiratory tract and lungs (choking sensation, chest tightness), respiratory sensitization, decreased ventilatory capacity, liver effects, cholinesterase depression, gastrointestinal distress and/or neurologic disorders. The 4-hour LC50 for TD1 for rats is 13.9 ppm.

SYSTEMIC & OTHER EFFECTS: This mixture contains a component which is listed as a potential carcinogen for hazard communication purposes under OSHA standard 29 CFR 1910.1200 (TDI, listed by NTP and IARC). An oral study in which high doses of TDI were reported to cause cancer in animals has been found to contain numerous deficiencies which compromise the validity of the study. TDI did not cause cancer in laboratory animals exposed by inhalation, the most likely route of exposure. Birth defects are unlikely from exposure to the TDI componenet. Exposures having no effect on the mother should have no effect on the fetus. TDI did not cause birth defects in animals; slight effects were seen in the fetus but only at doses which caused toxic effects to the mother. Results of in vitro ("test tube") mutagenicity tests have been inconclusive.

(Continued on Page 5)

(R) Indicates a Trademark of The Dow Chemical Company

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92066

Page: 5

PRODUCT NAME: VORANATE (R) 3071 ISOCYANATE

Effective Date: 12/27/88 Date Printed: 01/25/89 MSI

MSDS:001138

7. FIRST AID:

EYES: Irrigate with flowing water immediately and continuously for 15 minutes. Consult medical personnel.

SKIN: In case of contact, immediately flush skin with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Call a physician if irritation persists. Wash clothing before reuse. Destroy contaminated shoes.

INGESTION: Do not induce vomiting. Call a physician and/or transport to emergency facility immediately.

INHALATION: Remove to fresh air. If not breathing, give mouthto-mouth resuscitation. If breathing is difficult, give oxygen.

Call a physician.

NOTE TO PHYSICIAN: May cause tissue destruction leading to stricture. If lavage is performed, suggest endotracheal and/or esophagoscopic control. If burn is present, treat as any thermal burn, after decontamination. No specific antidote. Supportive care. Treatment based on judgment of the physician in response to reactions of the patient. The manifestations of reactions of the patient. The manifestations of the respiratory symptoms, including pulmonary edema, resulting from acute exposure may be delayed. May cause respiratory sensitization. Cholinesterase inhibition has been noted in human exposure but is not of benefit in determining exposure and is not correlated with signs of exposure.

8. HANDLING PRECAUTIONS:

EXPOSURE GUIDELINE(S): OSHA PEL is 0.02 ppm as a ceiling limit for toluene 2,4-diisocyanate. ACGIH TLV is 0.005 ppm; 0.02 ppm STEL for toluene 2,4-diisocyanate. Dow Industrial Hygiene Guide is 0.02 ppm as a ceiling limit for toluene diisocyanate.

VENTILATION: Provide general and/or local exhaust ventilation to control airborne levels below the exposure guidelines.

(Continued on Page 6)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

Dow Chemical U.S.A.* Midland, MI 48674 Emergency Phone: 517-636-4400

Product Code: 92066

Page: 6

PRODUCT NAME: VORANATE (R) 3071 ISOCYANATE

Effective Date: 12/27/88 Date Printed: 01/25/89

MSDS:001138

8. HANDLING PRECAUTIONS: (CONTINUED)

RESPIRATORY PROTECTION: Atmospheric levels should be maintained below the exposure guideline. When respiratory protection is required for certain operations, use an approved supplied-air respirator. For emergency and other conditions where the exposure guideline may be greatly exceeded, use an approved positive-pressure self-contained breathing apparatus.

SKIN PROTECTION: Use protective clothing impervious to this material. Selection of specific items such as gloves, boots, apron, or full-body suit will depend on operation. Remove contaminated clothing immediately, wash skin area with soap and water, and launder clothing before reuse. Safety shower should be located in immediate work area.

EYE PROTECTION: Use chemical goggles. If vapor exposure causes eye irritation, use a full-face, supplied-air respirator. Eye wash fountain should be located in immediate work area.

9. ADDITIONAL INFORMATION:

REGULATORY REQUIREMENTS:

SARA HAZARD CATEGORY: This product has been reviewed according to the EPA 'Hazard Categories' promulgated under Sections 311 and 312 of the Superfund Amendment and Reauthorization Act of 1986 (SARA Title III) and is considered, under applicable definitions, to meet the following categories:

An immediate health hazard A delayed health hazard A reactive hazard

SPECIAL PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE: Prevent all contact; warning properties of this material (irritation of eyes, nose, and throat) are not adequate to prevent chronic

(Continued on Page 7)
(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

Midland, MI 48674 Emergency Phone: 517-636-4400 Dow Chemical U.S.A.*

Product Code: 92066

PRODUCT NAME: VORANATE (R) 3071 ISOCYANATE

Effective Date: 12/27/88 Date Printed: 01/25/89

MSDS:001138

ADDITIONAL INFORMATION: (CONTINUED)

overexposure from inhalation. This material can produce asthmatic sensitization upon either single inhalation exposure to a relatively high concentration or upon repeated inhalation exposure to lower concentrations. Exposures to vapors of heated TDI can be extremely dangerous.

MSDS STATUS: Revised Sections 1, 3, 5, 6, and 7.

SARA 313 INFORMATION:

This product contains the following substances subject to the reporting requirements of section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR Part 372:

CHEMICAL NAME	CAS NUMBER	CONCENTRATION	
TOLUENE-2,6-DIISOCYANATE TOLUENE-2,4-DIISOCYANATE	000091-08-7	<60	%
	000584-84-9	<60	%

⁽R) Indicates a Trademark of The Dow Chemical Company The Information Herein Is Given In Good Faith, But No Warranty, Express Or Implied, Is Made. Consult The Dow Chemical Company For Further Information.

FF 568-B (2-86)

GENERAL (ELECTRIC

General Electric Company

RETURN POSTAGE GUARANTEED

P.O. BOX 2223 DECATUR, ALA 35609-2223

> Document Processing Center Office of Toxic Substances, TS-790 U.S. Environmental Protection Agency 401 M Street, S.W. Washington, D.C. 20460

